

Product Family	Terminals	10727849
r todace r anniy		10/2/019
		GCN Number
Series	120090;120031;120149;120086;120087;120088;120092;120195;120206;12 0315;	December 01, 2015
		Date Issued
Reason For Change	Supplier Change	
Change Description	The purpose of this letter is to inform you that Molex Polska will add 2nd source for terminal 1202060013. This change is being made to reduce delivery risks and more risks. Both vendors will be producing the raw material to the same material spece. Molex so there will be no risk in form, fit and function. Qualification data will be a request.	aterial supply provided by
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Special Request	
Assessment Of Change (How Product Will Be Qualified & Validated)	Molex internal test	
Internal Molex Qualification Date (Planned Date Information Available)	September 01, 2015	
Sample Availability Date (Changed Part)	September 01, 2015	
Date of Implementation	December 07, 2015	
Method of Identifying Change	Information on the box	
Recommended Replacement Parts		
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com