

Harwin plc  
Fitzherbert Road  
Farlington, Portsmouth  
Hampshire PO6 1RT  
United Kingdom

Reception: +44 (0)23 9231 4545  
Sales Desk: +44 (0)23 9237 0451  
Fax: +44 (0)23 9231 4590

Monday 7<sup>th</sup> December, 2015

Dear Customer,

## Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of individual items that are now obsolete. **Some of these items have a Last Time Buy date of 4<sup>th</sup> March 2016** – please check the attached spreadsheet list for specific details. The rest of the items are obsolete with immediate effect; stocks may remain of a few items, but most of these have not been manufactured in more than 8 years. Please see the attached spreadsheet for a complete list of affected items (there are two sheets in the spreadsheet, please check both). Here is a summary of affected standard ranges:

- Extended SIL IC Sockets D01-950xxxx
- PLCC connectors: D830xxB-46, D830xxC-46, D840xxB-46
- Reeled PCB sockets starting S31xx, S80xx and S85xx
- A selection of special items

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team  
[technical@harwin.com](mailto:technical@harwin.com)

**If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.**