

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: All Customers, Sales Representatives and Distributors

Date: November 19, 2015

Subject: 87 Series Keypad Dome Contact Change

This Product Advisory Notice is to alert you that Grayhill is changing the dome contact for all 87 Series Standard and Custom Keypads.

Description of Change

Due to a supply chain issue on the current dome contact used on this keypad assembly, Grayhill will be temporarily changing the dome contact to a drop in equivalent dome effective immediately. This dome contact change will have no effect on the published specifications for this keypad series.

Reason for Change

The current supply chain issue has already delayed shipments by 8 weeks and threatens to delay them an additional 12 weeks. An alternative dome contact was immediately available from one of our existing suppliers. After extensive testing of both the dome and representative keypad assemblies, the alternate was approved for production.

Effective Date

November 19, 2015



PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

Part Numbers Affected

87AB3-201	87YY3201A-681	87YY3201A-710	87YY3204A-524	87YY3206A-521
87AC3-201	87YY3201A-682	87YY3201A-711	87YY3204A-529	87YY3206A-522
87BB3-201	87YY3201A-683	87YY3201A-712	87YY3204A-531	87YY3206A-523
87BC3-201	87YY3201A-684	87YY3201A-713	87YY3204A-546	87YY3612A-510
87CC3-201	87YY3201A-685	87YY3201A-714	87YY3204A-552	87YY3616A-514
87DC3-201	87YY3201A-686	87YY3201A-715	87YY3204A-553	87YY3616A-515
87EC3-201	87YY3201A-687	87YY3201A-716	87YY3204A-570	87YY3616A-519
87FC3-201	87YY3201A-688	87YY3201A-717	87YY3204A-571	87YY3616A-529
87GC3-201	87YY3201A-689	87YY3201A-718	87YY3204A-572	87YY3616A-530
87HC3-201	87YY3201A-690	87YY3201A-719	87YY3204A-573	87YY3616A-534
87YY3201A-507	87YY3201A-691	87YY3202A-520	87YY3204A-574	87YY3616A-539
87YY3201A-544	87YY3201A-692	87YY3202A-532	87YY3204A-575	87YY3616A-541
87YY3201A-545	87YY3201A-693	87YY3202A-549	87YY3205A-509	87YY3616A-543
87YY3201A-546	87YY3201A-694	87YY3203A-546	87YY3205A-510	87YY5000-1
87YY3201A-547	87YY3201A-698	87YY3203A-547	87YY3205A-515	87YY5004
87YY3201A-548	87YY3201A-700	87YY3203A-548	87YY3205A-519	87YY5007
87YY3201A-583	87YY3201A-701	87YY3203A-549	87YY3205A-520	
87YY3201A-586	87YY3201A-702	87YY3203A-550	87YY3205A-526	
87YY3201A-587	87YY3201A-703	87YY3203A-566	87YY3205A-532	
87YY3201A-613	87YY3201A-704	87YY3203A-567	87YY3206A-513	
87YY3201A-659	87YY3201A-705	87YY3204A-502	87YY3206A-514	
87YY3201A-660	87YY3201A-706	87YY3204A-504	87YY3206A-517	
87YY3201A-661	87YY3201A-707	87YY3204A-505	87YY3206A-518	
87YY3201A-671	87YY3201A-708	87YY3204A-513	87YY3206A-519	
87YY3201A-680	87YY3201A-709	87YY3204A-520	87YY3206A-520	

Action Required

Please forward this notification to the appropriate person(s) in your organization. No other action is required. However, if you would like to receive a copy of the test reports, please contact your Grayhill, Inc. Sales Associate.

