



Title of Change:	Update Notice of FPCN21129X - Qualification Vehicle Model correction.																				
Proposed first ship date:	14 March 2016																				
Contact information:	Contact your local ON Semiconductor Sales Office or < Tsutomu Shimazaki@ onsemi.com > < Takashi.Harashima@onsemi.com>< Takeshi2.Hoshino @onsemi.com>< Kazumi. Onda@onsemi.com> < Shinya Okada@onsemi.com>< Yoshiyuki Nunokawa@onsemi.com>																				
Samples:	Contact your local ON Semiconductor Sales Office or < jun.hasunuma@onsemi.com>																				
Additional Reliability Data:	Contact your local ON Semiconductor Sales Office or < Satoru.Fujinuma@onsemi.com>																				
Type of notification:	ON Semiconductor will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, contact <PCN.Support@onsemi.com>.																				
Change category:	<input type="checkbox"/> Wafer Fab Change <input checked="" type="checkbox"/> Assembly Change <input type="checkbox"/> Test Change <input type="checkbox"/> Other _____																				
Change Sub-Category(s):	<input type="checkbox"/> Manufacturing Site Change/Addition <input checked="" type="checkbox"/> Material Change <input type="checkbox"/> Datasheet/Product Doc change <input type="checkbox"/> Manufacturing Process Change <input type="checkbox"/> Product specific change <input type="checkbox"/> Shipping/Packaging/Marking <input type="checkbox"/> Other: _____																				
Sites Affected:	<input type="checkbox"/> All site(s) <input type="checkbox"/> not applicable <input checked="" type="checkbox"/> ON Semiconductor site(s) : <input type="checkbox"/> External Foundry/Subcon site(s) ON Tarlac City, Philippines																				
Description and Purpose:	<p>This Update Notification is issued to customers to correct the Qualification Vehicle model names of the list of affected Standard parts for the previously released FPCN21129X.</p> <p>LV8711V-TLM-H → correct → LV8111V-TLM-H</p> <p>FPCN21129X was previously issued to announce the contents below:</p> <ol style="list-style-type: none"> 1) Gold wire connecting chip and Lead will be changed to Copper wire. 2) Mold resin will be changed to suitable Copper wire. <p>There is no change of the electrical characteristic specifications with this changing.</p>																				
List of Affected Standard Parts:	<table border="1"> <thead> <tr> <th>Part Number</th> <th>Qualification Vehicle</th> </tr> </thead> <tbody> <tr> <td>LV8729V-TLM-H</td> <td>LV8111V-TLM-H</td> </tr> <tr> <td>LV8731V-TLM-H</td> <td>LV8111V-TLM-H</td> </tr> <tr> <td>LV8732V-TLM-H</td> <td>LV8111V-TLM-H</td> </tr> <tr> <td>LV8732VL-TLM-H</td> <td>LV8111V-TLM-H</td> </tr> <tr> <td>LV8734V-TLM-H</td> <td>LV8111V-TLM-H</td> </tr> <tr> <td>LV8734VL-TLM-H</td> <td>LV8111V-TLM-H</td> </tr> <tr> <td>LV8735V-TLM-H</td> <td>LV8111V-TLM-H</td> </tr> <tr> <td>LV8736V-TLM-H</td> <td>LV8111V-TLM-H</td> </tr> </tbody> </table>			Part Number	Qualification Vehicle	LV8729V-TLM-H	LV8111V-TLM-H	LV8731V-TLM-H	LV8111V-TLM-H	LV8732V-TLM-H	LV8111V-TLM-H	LV8732VL-TLM-H	LV8111V-TLM-H	LV8734V-TLM-H	LV8111V-TLM-H	LV8734VL-TLM-H	LV8111V-TLM-H	LV8735V-TLM-H	LV8111V-TLM-H	LV8736V-TLM-H	LV8111V-TLM-H
Part Number	Qualification Vehicle																				
LV8729V-TLM-H	LV8111V-TLM-H																				
LV8731V-TLM-H	LV8111V-TLM-H																				
LV8732V-TLM-H	LV8111V-TLM-H																				
LV8732VL-TLM-H	LV8111V-TLM-H																				
LV8734V-TLM-H	LV8111V-TLM-H																				
LV8734VL-TLM-H	LV8111V-TLM-H																				
LV8735V-TLM-H	LV8111V-TLM-H																				
LV8736V-TLM-H	LV8111V-TLM-H																				