





ASSEMBLY INSTRUCTION

NC3FX-TOP & NC5FX-TOP | XLR Cable Connector

IP65 RATED AND UL50E APPROVED.



A Cut cable end approx. 45°.


B Slide the bushing over the cable.

To ease the boot assembly apply some cable pulling lubricant to the cable ends.


C Prepare cable as shown.

D Insert wires into the terminals and SOLDER them.

Wiring: 3 pole



5 pole



E Put chuck onto the cable.


Attention: Pay attention to the guiding key.

F Slide insert and chuck together into the housing.

Important: Align the insert by positioning as shown.

G Finish the installation by turning the bushing onto the connector.

Attention: Screw the bushing to the end of the thread.



FINISHED



NEUTRIK AG
NEUTRIK USA Inc.
NEUTRIK (UK) Ltd.
NEUTRIK Vertriebs GmbH

LI
USA
UK
DE/NL/AT/DK

T: +423 / 237 24 24
T: +1 704 / 972 3050
T: +44 1983 / 811 441
T: +49 8131 / 280 890

F: +423 / 232 53 93
F: +1 704 / 438 9202
F: +44 1983 / 811 439
F: +49 8131 / 280 830

NEUTRIK France
NEUTRIK Tokyo Ltd.
NEUTRIK Hong Kong Ltd.
NEUTRIK India Pvt. Ltd.

FR
JP
HK
IND

T: +33 1 / 4131 6750
T: +81 3 / 3663 4733
T: +852 / 2687 6055
T: +91 / 982 05 43 424

F: +33 1 / 4131 0511
F: +81 3 / 3663 4796
F: +852 / 2687 6052
F: +91 / 22 26163 540

Draft. Nr.: BDA 549 | Update: 06.09.2018 | Data subject to change without prior notice. ©2018 NEUTRIK®. ALL RIGHTS RESERVED. NEUTRIK® is a registered trademark.

www.neutrik.com

NEUTRIK®