



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PCN#20181205001.0

**Pin One Dot Symbolization change – Adding Pin One Dot for Select SC70, SOT-23,
and SOT-223 Devices
Information Only**

Date: January 07, 2019
To: Newark/Farnell PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only. Please see the attachment details for the planned implementation date.

This notification period is per TI's standard process. Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

20181205001.0
Attachment: 1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
DS90LT012AQM/NOPB	null
DS90LT012AQMFE/NOPB	null
DS90LT012ATMF/NOPB	null
DS90LV011AQM/NOPB	null
DS90LV011AQMFE/NOPB	null
DS90LV011ATMF/NOPB	null
DS90LV012ATMF/NOPB	null
LM1117IMP-3.3/NOPB	null
LM1117IMP-5.0/NOPB	null
LM1117IMP-ADJ/NOPB	null
LM1117IMPX-3.3/NOPB	null
LM1117IMPX-5.0/NOPB	null
LM1117IMPX-ADJ/NOPB	null
LM1117MP-1.8/NOPB	null
LM1117MP-2.5/NOPB	null
LM1117MP-3.3/NOPB	null
LM1117MP-5.0/NOPB	null
LM1117MP-ADJ/NOPB	null
LM1117MPX-1.8/NOPB	null
LM1117MPX-2.5/NOPB	null
LM1117MPX-3.3/NOPB	null
LM1117MPX-5.0/NOPB	null
LM1117MPX-ADJ/NOPB	null
LM20BIM7/NOPB	null
LM2611AMF/NOPB	null
LM2611BMF/NOPB	null
LM26CIM5-NPA/NOPB	null
LM26CIM5-SHA/NOPB	null
LM26CIM5-SPA/NOPB	null
LM26CIM5-TPA/NOPB	null
LM2704MF-ADJ/NOPB	null
LM27313XMF/NOPB	null
LM27313XMF/NOPB	null
LM2731XMF/NOPB	null
LM2731YMF/NOPB	null
LM2733XMF/NOPB	null
LM2733YMF/NOPB	null
LM2735XMF/NOPB	null
LM2735XQMF/NOPB	null
LM2735YMF/NOPB	null
LM2735YQMF/NOPB	null
LM2767M5/NOPB	null
LM2830XMF/NOPB	null
LM2831XMF/NOPB	null
LM2831YMF/NOPB	null
LM2831ZMF/NOPB	null
LM2936MP-3.0/NOPB	null
LM2936MP-3.3/NOPB	null
LM2936MP-5.0/NOPB	null
LM2937IMP-10/NOPB	null
LM2937IMP-12/NOPB	null
LM2937IMP-2.5/NOPB	null
LM2937IMP-3.3/NOPB	null
LM2937IMP-5.0/NOPB	null
LM2937IMP-8.0/NOPB	null
LM2937IMPX-15/NOPB	null
LM2937IMPX-5.0/NOPB	null
LM2940IMP-10/NOPB	null

LM2940IMP-12/NOPB	null
LM2940IMP-15/NOPB	null
LM2940IMP-5.0/NOPB	null
LM2940IMP-9.0/NOPB	null
LM317AEMP/NOPB	null
LM317AEMPX/NOPB	null
LM317EMP/NOPB	null
LM317EMPX/NOPB	null
LM321MF/NOPB	null
LM321MFX/NOPB	null
LM337IMP/NOPB	null
LM337IMPX/NOPB	null
LM340MP-5.0/NOPB	null
LM3410XMF/NOPB	null
LM3410XQMF/NOPB	null
LM3410YMF/NOPB	null
LM3411M5-5.0/NOPB	null
LM3475MF/NOPB	null
LM3480IM3-12/NOPB	null
LM3480IM3-15/NOPB	null
LM3480IM3-3.3/NOPB	null
LM3480IM3-5.0/NOPB	null
LM3480IM3X-3.3/NOPB	null
LM3480IM3X-5.0/NOPB	null
LM3670MF-1.2/NOPB	null
LM3670MF-3.3/NOPB	null
LM3670MF-ADJ/NOPB	null
LM3671MF-1.2/NOPB	null
LM3671MF-1.5/NOPB	null
LM3671MF-1.8/NOPB	null
LM3671MF-2.5/NOPB	null
LM3671MF-3.3/NOPB	null
LM3671MF-ADJ/NOPB	null
LM3674MF-1.2/NOPB	null
LM3674MF-ADJ/NOPB	null
LM3724IM5-3.08/NOPB	null
LM3724IM5-4.63/NOPB	null
LM385M3-1.2/NOPB	null
LM385M3-2.5/NOPB	null
LM3940IMP-3.3/NOPB	null
LM3940IMPX-3.3/NOPB	null
LM397MF/NOPB	null
LM397MFX/NOPB	null
LM4030AMF-2.5/NOPB	null
LM4030AMF-4.096/NOPB	null
LM4030CMF-2.5/NOPB	null
LM4030CMF-4.096/NOPB	null
LM4040AIM3-10.0/NOPB	null
LM4040AIM3-2.0/NOPB	null
LM4040AIM3-2.5/NOPB	null
LM4040AIM3-3.0/NOPB	null
LM4040AIM3-4.1/NOPB	null
LM4040AIM3-5.0/NOPB	null
LM4040AIM3X-2.5/NOPB	null
LM4040AIM3X-5.0/NOPB	null
LM4040BIM3-10.0/NOPB	null
LM4040BIM3-2.0/NOPB	null
LM4040BIM3-2.5/NOPB	null
LM4040BIM3-3.0/NOPB	null
LM4040BIM3-4.1/NOPB	null
LM4040BIM3-5.0/NOPB	null
LM4040BIM3X-2.5/NOPB	null
LM4040CEM3-5.0/NOPB	null
LM4040CIM3-10.0/NOPB	null
LM4040CIM3-2.0/NOPB	null
LM4040CIM3-2.5/NOPB	null
LM4040CIM3-3.0/NOPB	null
LM4040CIM3-4.1/NOPB	null
LM4040CIM3-5.0/NOPB	null
LM4040CIM3X-2.5/NOPB	null
LM4040CIM3X-4.1/NOPB	null

LM4040DEM3-5.0/NOPB	null
LM4040DIM3-10.0/NOPB	null
LM4040DIM3-2.5/NOPB	null
LM4040DIM3-3.0/NOPB	null
LM4040DIM3-4.1/NOPB	null
LM4040DIM3-5.0/NOPB	null
LM4040DIM3X-2.5/NOPB	null
LM4040DIM3X-4.1/NOPB	null
LM4040DIM3X-5.0/NOPB	null
LM4040EIM3-2.5/NOPB	null
LM4041AIM3-1.2/NOPB	null
LM4041BIM3-1.2/NOPB	null
LM4041CEM3-1.2/NOPB	null
LM4041CEM3-ADJ/NOPB	null
LM4041CIM3-1.2/NOPB	null
LM4041CIM3-ADJ/NOPB	null
LM4041CIM3X-ADJ/NOPB	null
LM4041CIM7-1.2/NOPB	null
LM4041CIM7-ADJ/NOPB	null
LM4041DIM3-1.2/NOPB	null
LM4041DIM3-ADJ/NOPB	null
LM4041EIM3-1.2/NOPB	null
LM4041QCEM3-1.2NO	null
LM4041QEEM3-1.2/NO	null
LM4050AIM3-2.5/NOPB	null
LM4050AIM3-4.1/NOPB	null
LM4050BIM3-2.5/NOPB	null
LM4050BIM3-5.0/NOPB	null
LM4050CIM3-2.5/NOPB	null
LM4050CIM3-4.1/NOPB	null
LM4050CIM3-5.0/NOPB	null
LM4051AIM3-1.2/NOPB	null
LM4051AIM3-ADJ/NOPB	null
LM4051BIM3-ADJ/NOPB	null
LM4051CIM3-ADJ/NOPB	null
LM4120AIM5-1.8/NOPB	null
LM4120AIM5-2.0/NOPB	null
LM4120AIM5-2.5/NOPB	null
LM4120AIM5-3.0/NOPB	null
LM4120AIM5-3.3/NOPB	null
LM4120AIM5-4.1/NOPB	null
LM4120AIM5-5.0/NOPB	null
LM4120IM5-2.0/NOPB	null
LM4120IM5-2.5/NOPB	null
LM4120IM5-3.0/NOPB	null
LM4120IM5-3.3/NOPB	null
LM4120IM5-4.1/NOPB	null
LM4120IM5-5.0/NOPB	null
LM4121AIM5-1.2/NOPB	null
LM4128AMF-3.3/NOPB	null
LM4128AMF-4.1/NOPB	null
LM4128BMF-2.5/NOPB	null
LM4132AMF-1.8/NOPB	null
LM4132AMF-2.0/NOPB	null
LM4132AMF-2.5/NOPB	null
LM4132AMF-3.0/NOPB	null
LM4132AMF-3.3/NOPB	null
LM4132BMF-2.0/NOPB	null
LM4132BMF-4.1/NOPB	null
LM4132CMF-2.5/NOPB	null
LM4132EMF-2.5/NOPB	null
LM4132EMF-3.0/NOPB	null
LM431ACM3/NOPB	null
LM431AIM3/NOPB	null
LM431AIM3X/NOPB	null
LM431BCM3/NOPB	null
LM431BIM3/NOPB	null
LM431BIM3X/NOPB	null
LM431CCM3/NOPB	null
LM431CIM3/NOPB	null
LM4431M3-2.5/NOPB	null

LM45BIM3/NOPB	null
LM45CIM3/NOPB	null
LM45CIM3X/NOPB	null
LM50BIM3/NOPB	null
LM50BIM3X/NOPB	null
LM50CIM3/NOPB	null
LM50CIM3X/NOPB	null
LM60BIM3/NOPB	null
LM60BIM3X/NOPB	null
LM60CIM3/NOPB	null
LM60CIM3X/NOPB	null
LM61BIM3/NOPB	null
LM61CIM3/NOPB	null
LM6211MF/NOPB	null
LM62BIM3/NOPB	null
LM62CIM3/NOPB	null
LM7121IM5/NOPB	null
LM7301IM5/NOPB	null
LM7321MF/NOPB	null
LM7321MFE/NOPB	null
LM7321QMFE/NOPB	null
LM7341MF/NOPB	null
LM7341MFE/NOPB	null
LM809M3-2.63/NOPB	null
LM809M3-2.93	null
LM809M3-2.93/NOPB	null
LM809M3-3.08	null
LM809M3-3.08/NOPB	null
LM809M3-4.38/NOPB	null
LM809M3-4.63/NOPB	null
LM809M3X-4.63/NOPB	null
LM810M3-4.63/NOPB	null
LM8261M5/NOPB	null
LM8261M5X/NOPB	null
LM828M5/NOPB	null
LM8364BALMF20/NOPB	null
LM8365BALMF27/NOPB	null
LM94021BIMG/NOPB	null
LM94022BIMG/NOPB	null
LM94022QBIMG/NOPB	null
LM95071CIMF/NOPB	null
LM95071CIMFX/NOPB	null
LMC7101AIM5/NOPB	null
LMC7101BIM5/NOPB	null
LMC7101BIM5X/NOPB	null
LMC7101QM5/NOPB	null
LMC7111BIM5/NOPB	null
LMC7111BIM5X/NOPB	null
LMC7211AIM5/NOPB	null
LMC7211BIM5/NOPB	null
LMC7211BIM5X/NOPB	null
LMC7215IM5/NOPB	null
LMC7221AIM5/NOPB	null
LMC7221AIM5X/NOPB	null
LMC7221BIM5/NOPB	null
LMC7225IM5/NOPB	null
LMH6559MF/NOPB	null
LMH6609MF/NOPB	null
LMH6624MF/NOPB	null
LMH6629MFE/NOPB	null
LMH6642MF/NOPB	null
LMH6645MF/NOPB	null
LMH6657MF/NOPB	null
LMH6702MF/NOPB	null
LMH6714MF/NOPB	null
LMH6723MF/NOPB	null
LMP2011MF/NOPB	null
LMP2021MFE/NOPB	null
LMP2231AMFE/NOPB	null
LMP7701MF/NOPB	null
LMP7707MF/NOPB	null

LMP7715MF/NOPB	null
LMP7717MF/NOPB	null
LMP7731MF/NOPB	null
LMR10510XMF/NOPB	null
LMR10510XMFE/NOPB	null
LMR10515XMF/NOPB	null
LMR10515YMF/NOPB	null
LMR10515YMFE/NOPB	null
LMR62014XMF/NOPB	null
LMR62014XMFE/NOPB	null
LMR62014XMF/NOPB	null
LMR62421XMFE/NOPB	null
LMR64010XMF/NOPB	null
LMR64010XMFE/NOPB	null
LMS33460MG/NOPB	null
LMS8117AMP-3.3/NOPB	null
LMS8117AMP-ADJ/NOPB	null
LMT84DCKT	null
LMT84QDCKTQ1	null
LMT85DCKT	null
LMT85QDCKTQ1	null
LMT86DCKT	null
LMT86QDCKTQ1	null
LMT87DCKR	null
LMT87DCKT	null
LMT87QDCKTQ1	null
LMT88DCKT	null
LMT89DCKT	null
LMT90DBZT	null
LMV116MF/NOPB	null
LMV2011MF/NOPB	null
LMV321M5/NOPB	null
LMV321M5X/NOPB	null
LMV321M7/NOPB	null
LMV331M5/NOPB	null
LMV331M5X/NOPB	null
LMV331M7/NOPB	null
LMV431ACM5/NOPB	null
LMV431AIM5/NOPB	null
LMV431AIM5X/NOPB	null
LMV431AIMF/NOPB	null
LMV431AIMFX/NOPB	null
LMV431BIMF/NOPB	null
LMV431CM5/NOPB	null
LMV431IM5/NOPB	null
LMV551MF/NOPB	null
LMV551MG/NOPB	null
LMV611MF/NOPB	null
LMV641MG/NOPB	null
LMV641MGE/NOPB	null
LMV651MF/NOPB	null
LMV651MG/NOPB	null
LMV710M5/NOPB	null
LMV7219M5/NOPB	null
LMV7219M5X/NOPB	null
LMV7219M7/NOPB	null
LMV721M5/NOPB	null
LMV721M7/NOPB	null
LMV7235M5/NOPB	null
LMV7239M5/NOPB	null
LMV7239M7/NOPB	null
LMV7271MF/NOPB	null
LMV7271MG/NOPB	null
LMV7275MF/NOPB	null
LMV7275MG/NOPB	null
LMV7291MG/NOPB	null
LMV751M5/NOPB	null
LMV771MG/NOPB	null
LMV793MF/NOPB	null
LMV796MF/NOPB	null
LMV821M5/NOPB	null

LMV821M5X/NOPB	null
LMV821M7/NOPB	null
LMV831MG/NOPB	null
LMV831MGE/NOPB	null
LMV841MG/NOPB	null
LMV861MG/NOPB	null
LMV931MF/NOPB	null
LMV931MFX/NOPB	null
LMV931MG/NOPB	null
LP2980AIM5-2.5/NOPB	null
LP2980AIM5-3.0/NOPB	null
LP2980AIM5-3.3/NOPB	null
LP2980AIM5-5.0/NOPB	null
LP2980AIM5X-3.3/NOPB	null
LP2980IM5-2.5/NOPB	null
LP2980IM5-3.0/NOPB	null
LP2980IM5-3.3/NOPB	null
LP2980IM5-5.0/NOPB	null
LP2980IM5-ADJ/NOPB	null
LP2980IM5X-3.3/NOPB	null
LP2980IM5X-5.0/NOPB	null
LP2980IM5X-ADJ/NOPB	null
LP2981AIM5-2.5/NOPB	null
LP2981AIM5-3.3/NOPB	null
LP2981AIM5-5.0/NOPB	null
LP2981IM5-2.5/NOPB	null
LP2981IM5-3.3/NOPB	null
LP2981IM5-5.0/NOPB	null
LP2982AIM5-3.0/NOPB	null
LP2982AIM5-3.3/NOPB	null
LP2982AIM5-5.0/NOPB	null
LP2982IM5-3.0/NOPB	null
LP2982IM5-3.3/NOPB	null
LP2982IM5-5.0/NOPB	null
LP2983AIM5-1.2/NOPB	null
LP2985AIM5-1.5/NOPB	null
LP2985AIM5-1.8/NOPB	null
LP2985AIM5-2.5/NOPB	null
LP2985AIM5-2.7/NOPB	null
LP2985AIM5-2.8/NOPB	null
LP2985AIM5-3.0/NOPB	null
LP2985AIM5-3.1/NOPB	null
LP2985AIM5-3.3/NOPB	null
LP2985AIM5-3.6/NOPB	null
LP2985AIM5-4.0/NOPB	null
LP2985AIM5-4.5/NOPB	null
LP2985AIM5-5.0/NOPB	null
LP2985AIM5X-3.3/NOPB	null
LP2985AIM5X-5.0/NOPB	null
LP2985IM5-1.8/NOPB	null
LP2985IM5-2.5/NOPB	null
LP2985IM5-2.8/NOPB	null
LP2985IM5-3.0/NOPB	null
LP2985IM5-3.3/NOPB	null
LP2985IM5-3.5/NOPB	null
LP2985IM5-3.6/NOPB	null
LP2985IM5-4.0/NOPB	null
LP2985IM5-4.5/NOPB	null
LP2985IM5-5.0/NOPB	null
LP2985IM5X-5.0/NOPB	null
LP2992AIM5-1.5/NOPB	null
LP2992AIM5-1.8/NOPB	null
LP2992AIM5-2.5/NOPB	null
LP2992AIM5-3.3/NOPB	null
LP2992AIM5-5.0/NOPB	null
LP2992IM5-1.5/NOPB	null
LP2992IM5-1.8/NOPB	null
LP2992IM5-2.5/NOPB	null
LP2992IM5-3.0/NOPB	null
LP2992IM5-3.3/NOPB	null
LP2992IM5-5.0/NOPB	null

LP3470IM5-3.08/NOPB	null
LP3470IM5-4.38/NOPB	null
LP3470IM5-4.63/NOPB	null
LP3470M5-2.93/NOPB	null
LP3470M5-4.00/NOPB	null
LP3470M5-4.63	null
LP3470M5-4.63/NOPB	null
LP3855EMP-ADJ/NOPB	null
LP38692MP-3.3/NOPB	null
LP38692MP-5.0/NOPB	null
LP38692MP-ADJ/NOPB	null
LP38693MP-1.8/NOPB	null
LP38693MP-3.3/NOPB	null
LP38693MP-5.0/NOPB	null
LP38693MP-ADJ/NOPB	null
LP3871EMP-2.5/NOPB	null
LP3871EMP-3.3/NOPB	null
LP3874EMP-3.3/NOPB	null
LP3874EMP-5.0/NOPB	null
LP3874EMP-ADJ/NOPB	null
LP3875EMP-3.3/NOPB	null
LP3875EMP-ADJ/NOPB	null
LP3961EMP-1.8/NOPB	null
LP3961EMP-2.5/NOPB	null
LP3961EMP-3.3/NOPB	null
LP3962EMP-2.5/NOPB	null
LP3964EMP-2.5/NOPB	null
LP3964EMP-3.3/NOPB	null
LP3964EMP-ADJ/NOPB	null
LP3965EMP-2.5/NOPB	null
LP3965EMP-3.3/NOPB	null
LP3965EMP-ADJ/NOPB	null
LP3985IM5-2.5/NOPB	null
LP3985IM5-2.7/NOPB	null
LP3985IM5-2.8/NOPB	null
LP3985IM5-3.0/NOPB	null
LP3985IM5-3.2/NOPB	null
LP3985IM5-3.3/NOPB	null
LP3985IM5-4.7/NOPB	null
LP3985IM5-5.0/NOPB	null
LP3985IM5X-3.3/NOPB	null
LP3988IMF-3.3/NOPB	null
LP3990MF-1.2/NOPB	null
LP3990MF-1.8/NOPB	null
LP3990MF-2.5/NOPB	null
LP3990MF-3.3/NOPB	null
LP3992IMFX-1.5/NOPB	null
LP5907MFX-1.2/NOPB	null
LP5907MFX-1.8/NOPB	null
LP5907MFX-2.5/NOPB	null
LP5907MFX-2.8/NOPB	null
LP5907MFX-2.9/NOPB	null
LP5907MFX-3.0/NOPB	null
LP5907MFX-3.3/NOPB	null
LP5907MFX-4.5/NOPB	null
LP5951MF-1.3/NOPB	null
LP5951MF-1.5/NOPB	null
LP5951MF-1.8/NOPB	null
LP5951MF-2.0/NOPB	null
LP5951MF-2.5/NOPB	null
LP5951MF-3.0/NOPB	null
LP5951MF-3.3/NOPB	null
LP5951MG-1.8/NOPB	null
LP5951MG-2.5/NOPB	null
LP5951MG-3.3/NOPB	null
LPV321M5/NOPB	null
LPV321M7/NOPB	null
LPV511MG/NOPB	null
LPV521MG/NOPB	null
LPV521MGE/NOPB	null
LPV7215MF/NOPB	null

LPV7215MG/NOPB	null
LPV801DBVT	null
LPV811DBVT	null
SM72501MFE/NOPB	null
TLV521DCKT	null
TLV76012DBZT	null
TLV76015DBZT	null
TLV76033DBZT	null
TLV76050DBZT	null
TLV8801DBVT	null
TLV8811DBVT	null
LM26CIM5-RPA/NOPB	null
LM26CIM5-VPA/NOPB	null
LM2703MF-ADJ/NOPB	null
LM2705MF-ADJ/NOPB	null
LM3724EM5-3.08/NOPB	null
LM4040BIM7-2.5/NOPB	null
LM4051BIM3-1.2/NOPB	null
LM4121AIM5-ADJ/NOPB	null
LM71CIMF/NOPB	null
LMR62421XMF/NOPB	null
LP2981IM5-3.0/NOPB	null







Technical details of this Product Change follow on the next page(s).

PCN Number:	20181205001	PCN Date:	Jan. 7, 2019
Title:	Pin One Dot Symbolization change – Adding Pin One Dot for Select SC70, SOT-23, and SOT-223 Devices		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Assembly Process
<input type="checkbox"/>	Design	<input type="checkbox"/>	Datasheet
<input type="checkbox"/>	Test Site	<input checked="" type="checkbox"/>	Packing/Shipping/Labeling
<input type="checkbox"/>	Wafer Bump Site	<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>	Wafer Fab Site	<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Part number change
<input type="checkbox"/>		<input type="checkbox"/>	Assembly Materials
<input type="checkbox"/>		<input type="checkbox"/>	Mechanical Specification
<input type="checkbox"/>		<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

PCN Details

Description of Change:

This letter is to inform of the addition of a Pin One dot in the devices symbolization of select SC70, SOT-23, and SOT-223 Devices:

	Current Symbolization (No Pin One Dot)	New Symbolization (With Pin One Dot)
SC70 Example		
SOT-23 3 Lead example		
SOT-23 5 Lead example		

**SOT-223 4
Lead example**



Reason for Change:

Standardization

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

None

Changes to product identification resulting from this PCN:

Device symbolization

Product Affected:

For affected devices, see page 2

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com