



22-Feb-2019

PCN #:P-19-016996

Subject:AMPMODU MTE HEADER ASSEMBLIES - CORRECTION TO PCN P-19-016981-LOCATION CHANGE FROM CHINA OUTSIDE VENDOR, NOT TE SUZHOU

Description of Change: Manufacturing location change. For any orders for an end customer location that is in the Americas, for the following part numbers, the manufacturing location will change from our outside vendor in China to our TE plant in Hermosillo, Mexico.

Reason: Dear Customer, In an effort to improve delivery and service to our customers, TE will modify our manufacturing footprint to better align to our customers region of consumption. As such, any orders for an end customer location that is in the Americas, for the following part numbers, the manufacturing location will change from our outside vendor in China to our TE plant in Hermosillo, Mexico. Any orders with end customer locations in Europe or Asia Pacific will continue to be produced at our outside vendor in China. There is no transfer of tooling with this manufacturing location change. TE guarantees that all quality standards, continuity of supply, and form-fit-function of affected products will be maintained. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees equivalent performance.

Key Dates:

Contact By Date:25-Apr-2019

Implementation Date:25-Apr-2019

Product Affected

5-103735-4

5-103639-2

5-103639-6

Product Affected

6-103735-6
2-103639-6
7-103639-4
6-103639-7
2-103735-2
3-103639-2
6-103639-2
2-103639-2
5-103639-9
2-103639-3
2-103639-9
5-103735-2
5-103735-5
6-103639-4
6-103735-2
7-103735-1
6-103735-1
7-103639-0
5-103639-5
7-103639-3
1-103735-2
3-103639-3
7-103735-2
7-103735-3
5-103735-6
6-103735-4
6-103735-0
2-103639-4
6-103639-8
5-103735-7
5-103639-7
6-103735-8
2-103639-7
5-103639-3
7-103735-0
5-103735-8
6-103639-5
5-103735-9
7-103639-1
6-103735-9

Product Affected

7-103735-4
6-103639-3
6-103735-7
2-103735-3
1-103639-7
6-103639-1
5-103735-1
6-103639-9
1-103735-8
2-103639-8
1-103735-7
5-103639-8
5-103639-4
2-103639-0
5-103735-3
2-103639-5
1-103639-8
6-103639-0
7-103639-2
6-103639-6
6-103735-5
6-103735-3
2-103735-0
3-103639-0
1-103639-6
5-103639-1
2-103735-1
3-103639-1
2-103735-4
1-103735-9
1-103735-6
1-103735-5
1-103735-4
1-103735-3
1-103735-1
1-103735-0
103735-9
103735-8
103735-7
103735-6

Product Affected

103735-5
103735-4
103735-3
103735-2
103735-1
2-103639-1
1-103639-9
1-103639-5
1-103639-4
1-103639-3
1-103639-2
1-103639-1
1-103639-0
103639-9
103639-8
103639-7
103639-6
103639-5
103639-4
103639-3
103639-2
103639-1
2-103638-4

(Alias Part Numbers:

"1166374")
2-103638-3
2-103638-2
2-103638-1
2-103638-0
1-103638-9
1-103638-8
1-103638-7
1-103638-6
1-103638-5
1-103638-4
1-103638-3
1-103638-2
1-103638-1

(Alias Part Numbers:

"2-42937-3651")

Product Affected

1-103638-0

103638-9

103638-8

(Alias Part Numbers:

"407161207")

103638-7

103638-6

103638-5

(Alias Part Numbers:

"407161199")

103638-4

103638-3

103638-2

(Alias Part Numbers:

"407085000")

103638-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.