



OVERVIEW

DATE ISSUED:	25 July 2019	TRACKING NUMBER:	4134700
ISSUED BY:	AirPrime Product Management		
PRODUCTS AFFECTED:	HL6528RD HL8518/8528/8529/8548/8549 HL7518/7548/7588 HL7618RD/7648/7688/7650/7690/7692		
SKUS AFFECTED:	All impacted products SKUs		
BULLETIN:	2 nd source PCB supplier introduction		
URGENCY:	Normal		
EFFECTIVE DATE:	1 Aug, 2019 (Detail milestones per each product as below)		
SAMPLE AVAILABILITY: (optional)	N/A		
FOR DISTRIBUTION TO:	All impacted products customers		

Summary

Dear Customer,

Sierra Wireless is informing customers of a second source PCB supplier introduction to secure product lifetime for products listed in this notification. Sierra Wireless has received a discontinuation notification from current PCB supplier. Sierra Wireless has consequently initiated a second source PCB qualification to replace the reference without changing any of the product specification and performance.

Details of Change

PCB structure, design, and materials are selected qualified and tested to ensure no impact to product specification and performance.

Effective Dates

This change is effective from 1st Aug, 2019. Detail milestones per each product as below:

HL6528RD: 1st Oct, 2019

HL8518/HL8528/HL8529: 1st Dec, 2019

HL8548/HL8549: 1st March, 2020

HL7518/HL7548/HL7588: 1st Aug, 2019

HL7618D/HL7688: 1st Aug 2019

HL7648: 1st Nov, 2019

HL7650/HL7690/HL7692: 1st March, 2020

More information

For more information please contact your Sierra Wireless sales/technical support person.