



Product Change Notification

End of Life Notification

Product Category : Intrusion Detection – Detectors / Sensors

Issue Date : 08/01/2019

Effective Date : 08/01/2019

LTB Date : N/A

LTD Date : N/A

Parts Effected : Below are the list of parts which are affected
With No Replacement

EOL PART NUMBERS			
27W47H	AS63	CS1221W	HBL363R6W
3SFBC	AT1277I	CS1222I	HBL3W40
AD1277BK1	AT1277W	CS1223W	HBL4P160
AD1277GY1	ATD1600W	CS1224I	HBL4P320
AD1277GY2	ATD500C	DJOGY	HBL4PS1050USB
AD1277I1N	ATD500CRP	DJOOW	HBL5262IS
AD1277I2	ATP120HB	FCX244OW	HBL5262WS
AD1277I2N	ATP1277GY	FCX444BK	HBL5360IS
AD1277LA1	ATP600C	FPR024STM	HBL5360S
AD1277W1N	ATP600CRP	FSPSCD6	HBL563P6W
AD1277W2	ATU1000C	GF15RL	HBL60CM83
AP1277GY1	ATU500C	HBL1386I	HBL6PSHG
AP1277GY1N	AU1277I1	HBL1PI750	HBL6RSPS2100
AP1277I1	AU1277I1N	HBL1PI750M	HBL8262S
AP1277I1N	AU1277W1	HBL316B6W	HBL8ESPS1050C
AP1277I2	AU1277W1N	HBL316C6W	HBL8ESPS1050M
AP1277W1	AU2000BK1N	HBL317SGY	HBL8W100
AP1277W1N	CR5262BK	HBL332P6W	HBLCON3
AP1277W2	CS1203I	HBL332R6W	HBLHI5E
AR151	CS1221GY	HBL363P6W	HBLHI5ESC
HBLHI6	HJ1015B	LVUS1500R120	USB20X2W



HBLHIC	HJ1015G	LVUS2000R120	USB4
HBLHISF11	HJ1038G	LVUS2000R277	USB4BK
HBLHIWP75GY	HJ1040B	P5E12B	USB4GY
HBLMAR2	HJ1055B	P5E12BF	USB4I
HBLORT322SGY	HJ1056B	P5E48UF19	USB4LA
HBLPHA4	HJ1057B	PCX6GY03	USB4W
HBLTCGNTSW	HJ1057G	SFST	USB8200GY
HBLTWPFF1GY	HJ1058B	SNAP8300USB	USB8200I
HJ1001B	HJ1058G	SNAP8300USBBK	VGA625BK
HJ1002B	HJ1059B	SNAP8300USBGY	WS120I
HJ1003B	HJ1060B	SNAP8300USBI	WS1277W2
HJ1004B	HJ1060G	SNAP8300USBLA	WS277I
HJ1005B	HKLD	SNAP8300USBR	WS277W
HJ1006B	HS1001G	SNAP8300USBW	-
HJ1011B	HS1004G	TWBP	-
HJ1012B	IG5362OS	USB15X2GY	-
HJ1013G	LVDT2000R120	USB15X2W	-
HJ1014B	LVDT2000R277	USB20X2GY	-
HJ1014G	LVPR1500RP	USB20X2I	-