

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Errata sheet affecting TLE986x and TLE987x BF step

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

N° 092/19

Errata sheet affecting TLE986x and TLE987x BF step

► **Products affected:**

Please refer to attached affected product list 1_cip09219

► **Detailed Change Information:**

Subject: Errata sheet affecting TLE986x and TLE987x BF step

Reason: Documented deviation from specification

Description:

Old

New

see 3_cip09219 errata sheets

► **Product Identification:**

not applicable

► **Impact of Change:**

No change of product in form, fit and function.

► **Attachments:**

1_cip09219 affected product list

3_cip09219 errata sheets



► **Intended start of delivery:**

not applicable

If you have any questions, please do not hesitate to contact your local Sales office.