

15.06.2020

OS-IN-2020-017

Adaption of product designation for BIDOS® family

Objective Adaption of product designation for BIDOS® family

Products affected

BIDOS® P2835 C
 PLPVCC2 850A
 PLPVCC2 850A_P
 PLPVCC2 940A
 PLPVCC2 940A_P
 PLPVDC2 940A_P
 PLPVDC3 940A_P
 PLPVDC6 940A_P
 PLPVEC1 850A
 PLPVEC2 850A
 PLPVEC2 940A

BIDOS® P2433 Q
 PLPVCQ 940B1_P

BIDOS® A2835 C
 PLPVDC4 940B A01
 PLPVEC6 850B A01
 PLPVEC6 940B A01

Background Introduction of new product designation to categorize family attributes considering future growth and complexity of BIDOS / OS VCSEL portfolio.

Realization	BIDOS® P2835 C	BIDOS® P2835 C
	Current product designation	New product designation
	PLPVCC2 850A	V102C021A-850
	PLPVCC2 850A_P	V102C121A-850
	PLPVCC2 940A	V102C021A-940
	PLPVCC2 940A_P	V102C121A-940
	PLPVDC2 940A_P	V105C121A-940
	PLPVDC3 940A_P	V105C131A-940

PLPVDC6 940A_P	V105C141A-940
PLPVEC1 850A	V107C000A-850
PLPVEC2 850A	V107C021A-850
PLPVEC2 940A	V107C021A-940

BIDOS® P2433 Q Current product designation	BIDOS® P2433 Q New product designation
PLPVCQ 940B1_P	V102Q123A-940

BIDOS® A2835 C Current product designation	BIDOS® A2835 C New product designation
PLPVDC4 940B A01	V105C022A-940 A01
PLPVEC6 850B A01	V107C051A-850 A01
PLPVEC6 940B A01	V107C051A-940 A01

Assessment

Update of product designation in documentation:

- Datasheet
- Supporting documents (rayfiles, material datasheets)
- Product label (BPL)

There is no change of the affected products.

Time Schedule

Documentation will be updated by 15th June 2020.

Please direct your inquiry to your local Sales office.