

Product Change Notice

PCN#:EE-PCN20002


April 1, 2020

CLASSIFICATION OF CHANGE:

Shrink Sleeve Marking

DESCRIPTION OF CHANGE:

Change negative lead indicator on all supercapacitor packs. New stripe will be visible from the side and from the ends at all angles.



Existing



New

REASON FOR CHANGE:

Improve customer auto placement machines optical read rates for proper orientation.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

None

PARTS FAMILIES AFFECTED:

PB family
PHB family
PHV family

TIME SCHEDULE:

Start Shipment
Date: June 15th, 2020

SAMPLE AVAILABILITY:

Not applicable

QUALIFICATION DATA:

Not applicable

ISSUED BY:

Product Manager: Jason Lee

CONTACT INFORMATION:

For questions or comments, please contact <https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html>