



26-May-2020

PCN #:E-20-003886

Subject:TERMINAL LOCATOR UPDATE

Description of Change: Terminal locator assembly 58516-2 is being replaced with a newer design that allows easier terminal support adjustments. This is a product improvement and does not affect current tools in the field. This change does not affect crimp quality of tools already in the field.

Reason: Product Improvement.

Key Dates:

Contact By Date:19-Jun-2020

Implementation Date:19-Jun-2020

Product Affected

2217266-2

2217266-1

2217208-1

2217267-1

2217268-1

2217267-2

2217208-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and

obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.