

Product Change Notification (PCN)

PCN Number 509106 Date Issued June 19, 2020 Reason for Change Obsolete Change Type Description This is to inform you that the part(s) referenced in this notice will be made obsolete. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s). Reason for Short Notice Force Majeure Planned Implementation Date June 30, 2020 Recommended Replacement Parts Please see the attached replacement parts list .xls file. Last Time Buy Date for Obsolete Parts June 19, 2020 Last Time Ship Date for Obsolete Parts June 19, 2020



After Change

Overview

- This is to notify our customers that we are obsoleting the list of parts attached to this notification with replacement.
- The reason for this obsolescence is due to tool crash, and we will not be able to continue production OBS harnesses.
 Hence, we are obsoleting with immediate effect and no LTB date.
- Part Number Impact and replacement part
 - See attached parts list



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:509106" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

PSZM	Customer #	Customer Name	Search Term	Molex Part #	Customer Material #	City	State	Country	Sales Engineer Name	Sales Engineer Email-ID
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138662433	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138662533	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138671633	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138671635	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138671637	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138672633	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138672635	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138672637	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138672733	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138672833	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138672933	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002138682033	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM
509106	0000104140	AVNET EMG FINANCEH601	AVNETEMG	000000002146571603	NPI	DALLAS	TX	US	TONY CIAPETTA	TONY.CIAPETTA@MOLEX.COM

Material	Replacement part number:	Replacement type (drop in replacement or replace with different)	Optional text if "replacement with differences"
2138662433	2138652433	Replacement with differences	Please check with sales engineer for the different
2138662533	2138652533	Replacement with differences	Please check with sales engineer for the different
2138671633	2138651633	Replacement with differences	Please check with sales engineer for the different
2138672633	2138652633	Replacement with differences	Please check with sales engineer for the different
2138672733	2138652733	Replacement with differences	Please check with sales engineer for the different
2138672833	2138652833	Replacement with differences	Please check with sales engineer for the different
2138672933	2138652933	Replacement with differences	Please check with sales engineer for the different
2138671635	2138651635	Replacement with differences	Please check with sales engineer for the different
2138672635	2138652635	Replacement with differences	Please check with sales engineer for the different
2138671637	2138651637	Replacement with differences	Please check with sales engineer for the different
2138672637	2138651637	Replacement with differences	Please check with sales engineer for the different
2138682033	2138652033	Replacement with differences	Please check with sales engineer for the different
2146571603	2146551633	Replacement with differences	Please check with sales engineer for the different
2138672603	2146552633	Replacement with differences	Please check with sales engineer for the different