

## PRODUCT CHANGE NOTIFICATION (PCN)

Product Category POWER CONNECTORS 20210215-1

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE:  **NA**  **EMEA**  **LATAM**  **AP** 20210215

IMPACTED REGIONS:  **DISCONTINUATION**

REASON FOR CHANGE:  **OTHER**

**DESCRIPTION OF CHANGE: (Required)**

Part collar manufacturing process is changing from extrusion to a stamped and formed design. All set screws are now internal hex key drive, previously some were slotted screws.

Discontinued  
Extrusion  
Version



Replacement  
Stamped and  
Formed  
Version



**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	3	15
Old product discontinuation date*	2021	5	31

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

**CUSTOMER SERVICE CONTACTS**

<b>ASIA PACIFIC</b>	<b>AUSTRALIA: 1-800 7263848</b> <a href="mailto:AUS-Customer-Service@panduit.com">AUS-Customer-Service@panduit.com</a>	<b>CHINA: 800-820-1900</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>HONG KONG: 800-965768</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	<b>INDIA: 000 800 6501844 (Fixed)</b> 000 800 6500369 (Mobile) <a href="mailto:IND-Customer_Service@panduit.com">IND-Customer_Service@panduit.com</a>	<b>INDONESIA: 001 803 65 7571</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>JAPAN: +81-3-6863-6000</b> <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	<b>TAIWAN: 0080 165 1487</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
<b>LATIN AMERICA</b>	<b>BRAZIL 08000562613 (Toll Free)</b> <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520</b> 01 800 360 86 00 (Toll Free) <a href="mailto:MEX-customer-service@panduit.com">MEX-customer-service@panduit.com</a>	<b>OTHER LA COUNTRIES:</b> Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>	
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b> <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>		

To add a contact or to unsubscribe, please send an email to:

[PCN@panduit.com](mailto:PCN@panduit.com)

Impacted Part Numbers	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
CB35-36-CY	Direct	CBS35-36-C			5/31/2021
CBA70-14-CY	Direct	CBS35-14-C			5/31/2021
CS35-36SL-CY	Direct	CSS35-36-C			5/31/2021
CSA70-14-CY	Direct	CSS35-14-C			5/31/2021
CD35-36SL-QY	Direct	CDS35-36-Q			5/31/2021
CO35-36SL-QY	Direct	COS35-36-Q			5/31/2021