

Product Change Notice

Issue Date: 09-March-2021

Change Description:

Alternate manufacturing site for ChipLED part numbers listed below

Parts Affected:

HSMA-C110	HSMM-C110	QSMC-C112
HSMC-C110	HSMN-C110	QSME-C111
HSMD-C110	HSMQ-C110	QSME-C112
HSME-C110	HSMR-C110	QSME-C113
HSMG-C110	HSMS-C110	QSME-C114
HSMH-C110	HSMY-C110	QSMQ-C111
HSM L-C110	HSMZ-C110	

Description and Extent of Change:

The alternate manufacturing site is qualified per Broadcom’s qualification process.







Reasons for Change:

Assurance of supply.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change on fit, form and function as per datasheet. Comparison of physical appearance between existing and alternate manufacturing sites is as shown in table below.

HSMx-C110 or QSMx-C11x or BSMx-C11x	Top View	Bottom View	Side View
--	-----------------	--------------------	------------------

Existing Site 1			
Existing Site 2			
Alternate Site			

Effective Date of Change:

Effective 3 month (from 15June2021), shipment may contain parts from existing or alternate manufacturing site.

Qualification Data:

Reliability data will be provided upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.