

**List of Affected Parts:**

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

Part Number	Qualification Vehicle
UC3845BVD1R2G	NA
UC3845BVD1G	NA
UC3845BD1R2G	NA
UC3845BD1G	NA
UC3844BVD1R2G	NA
UC3844BVD1G	NA
UC3844BD1R2G	NA
UC3844BD1G	NA
UC3843BVD1R2G	NA
UC3843BVD1G	NA
UC3843BD1R2G	NA
UC3843BD1G	NA
UC3842BVD1R2G	NA
UC3842BVD1G	NA
UC3842BD1R2G	NA
UC3842BD1G	NA
UC2845BD1R2G	NA
UC2845BD1G	NA
UC2844BD1R2G	NA
UC2843BD1R2G	NA
UC2843BD1G	NA
UC2842BD1R2G	NA
UC2842BD1G	NA

Japanese translation of the notification starts here.
通知の日本語訳はここから始まります。

Note: The Japanese version is for reference only. In case of any differences between the English and Japanese version, the English version shall control.

注：日本語版は参照用です。英語版と日本語版の違いがある場合は、英語版が優先されます。



影響を受ける部品の一覧:

注: 部品一覧には標準部品番号 (既製品) のみが記載されています。本 PCN の影響を受けるカスタム部品番号は、PCN メールで提供される顧客個別の付録、または PCN カスタマイズポータルに記載されています。

部品番号	認定試験用ピークル
UC3845BVD1R2G	NA
UC3845BVD1G	NA
UC3845BD1R2G	NA
UC3845BD1G	NA
UC3844BVD1R2G	NA
UC3844BVD1G	NA
UC3844BD1R2G	NA
UC3844BD1G	NA
UC3843BVD1R2G	NA
UC3843BVD1G	NA
UC3843BD1R2G	NA
UC3843BD1G	NA
UC3842BVD1R2G	NA
UC3842BVD1G	NA
UC3842BD1R2G	NA
UC3842BD1G	NA
UC2845BD1R2G	NA
UC2845BD1G	NA
UC2844BD1R2G	NA
UC2843BD1R2G	NA
UC2843BD1G	NA
UC2842BD1R2G	NA
UC2842BD1G	NA