


Light is OSRAM

Not For New Designs OS-NFND-2021-008

15 April 2021

Expected discontinuation date:	9/1/2021
Reason:	The following products have reached their end of life.
OSRAM OS Expectations:	Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products. Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.




Please direct your feedback to your local Sales office.

Not for new design products		Recommended Replacement			
Device	Brand	Device	Brand	Datasheet Ordering Code	Expected PDN start
SFH 3600	MIDLED	SFH 3219	TOPLED	Q62702P5551	Q3 2021
SFH 3605	MIDLED	SFH 3015FA	CHIPLED	Q65110A9730	Q3 2021
SFH 4140	MIDLED	SFH 4045N	CHIPLED	Q65111A3903	Q3 2021
SFH 4441	MIDLED	SFH 4248	Power TOPLED	Q65110A3304	Q3 2021
SFH 4441 E9621	MIDLED	SFH 4248	Power TOPLED	Q65110A3304	Q3 2021
SFH 4451	MIDLED	SFH 4258	Power TOPLED	Q65110A2976	Q3 2021
SFH 4451	MIDLED	SFH 4056	CHIPLED	Q65111A2992	Q3 2021
SFH 4640	MIDLED	SFH 4248	Power TOPLED	Q65110A3304	Q3 2021
SFH 4641	MIDLED	SFH 4544	Radial	Q65111A4886	Q3 2021
SFH 4645	MIDLED	SFH 4045N	CHIPLED	Q65111A3903	Q3 2021
SFH 4646	MIDLED	SFH 4045N	CHIPLED	Q65111A3903	Q3 2021
SFH 4650	MIDLED	SFH 4059S	CHIPLED	Q65111A0278	Q3 2021
SFH 4650	MIDLED	SFH 4258	Power TOPLED	Q65110A2976	Q3 2021
SFH 4651	MIDLED	SFH 4059	CHIPLED	Q65111A2991	Q3 2021
SFH 4655	MIDLED	SFH 4350	Radial	Q65110A2091	Q3 2021
SFH 4656	MIDLED	SFH 4551	Radial	Q65111A0506	Q3 2021
SFH 4656	MIDLED	SFH 4554	Radial	Q65111A4885	Q3 2021

Strategic Phase-out

**Customer Info Package for:
OS-NFND-2021-008
Status: April 2021**




Strategic Phase-out Customer Info Package

	Page
1. General Information	03
2. Strategic Phase-out MIDLED	05

1. General Information

Customer feedback mandatory




Customer has 3.5 Years to switch to the recommended replacement

Strategic Phase-out Customer Info Package

	Page
1. General Information	03
2. Strategic Phase-out MIDLED	05

2. Strategic Phase-out MIDLED

General overview




Reason: Based on several product changes in view of material discontinuation we are forced to discontinue all MIDLED devices. A 1:1 replacement is currently not possible.

Perspective:

- Our sales department will closely work with you to check on the demand for running projects and to generate a smooth phase out plan.
- Our application engineers will support you to find the best replacement product.
- Depending on the business case we will consider to develop a new MIDLED version.

2. Strategic Phase-out MIDLED

Planned time scenario for product phase-out



www.osram-os.com

Thank you.

OSRAM
Opto Semiconductors