



01-Jun-2021

PCN #:PCN-21-103907

Subject:AMPSEAL 16 Product Family Seal Material Change for Grommet (Matte) and Peripheral Seal Due to Supply Constraints

Description of Change: The Industrial and Commercial Transportation business unit of TE Connectivity is making a material change to the AS16 Grommet (Matte) and Peripheral Seal for the part number(s) listed below because of a material supply constraint. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. Product drawing(s) are not affected by this change.

Reason: Dear Customer, we hereby inform you of this change. This change is necessary to due to increased capacity and material constraints. The change will not impact connector performance. **IMPORTANT:** The current and previous revisions of these parts can be used interchangeably in the field. The change(s) may be phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

Key Dates:

Contact By Date:18-Jun-2021

Implementation Date:18-Jun-2021

Product Affected	Alias Part Number
------------------	-------------------

2320913-1	
-----------	--

776427-1	
----------	--

2320937-2	
-----------	--

2035368-1	
-----------	--

1456822-2	
-----------	--

Product Affected	Alias Part Number
776437-2	
2320913-3	
776536-4	
2320915-1	
2320927-4	
2320918-4	
776428-3	"BACA-AMP-216"
776538-2	
2035368-4	
2320932-2	
2098554-1	
2035370-1	
2320929-3	
2320936-3	
2098553-1	
2320931-1	
2320927-2	
2035381-3	
2320913-4	
776535-4	
2098238-1	
776438-2	
2320931-2	
2035378-4	
2320920-2	
2098238-3	
1456821-4	
2035368-2	
1456822-3	
776532-3	
2320923-1	
2320933-2	
2035379-3	
776427-4	"820P-37811"
776495-1	
776534-3	
2035561-3	
2320916-3	
2320920-4	
2320928-4	

Product Affected	Alias Part Number
2035379-2	
776522-1	
2320935-2	
2035381-1	
776537-3	
1456823-4	
1456823-1	
2320927-1	
2320914-3	
2098554-3	
2320932-1	
2320930-4	
2320928-2	
776535-1	
2320934-4	
2098554-4	
2098237-3	
2035370-2	
2320930-2	
776494-2	
776495-3	
2035369-2	
776433-1	
2320930-1	
776429-2	
2035560-4	
776494-1	
2098241-3	
2035367-2	
2320924-2	
776433-3	
2098241-1	
2035369-3	
2320921-2	
776524-4	
2320917-3	
776430-1	"820P-37694", "62105082-000"
2320928-1	
776537-1	
776427-2	"8202614013"

Product Affected	Alias Part Number
2320934-1	
776427-3	
2320931-3	
776428-4	
2035562-1	
2035381-4	
2320925-2	
2098556-1	
2098237-1	
2320927-3	
776430-4	
2320933-1	
2098241-2	
776536-3	
776534-1	
2035561-2	
2320915-4	
776434-1	
776539-2	
2320923-3	
2098556-2	
2320926-4	
2098553-3	
2320924-4	
2320928-3	
2320921-1	
2035368-3	
2098553-2	
776429-1	"820P-37699"
776429-3	
776524-3	
2098555-3	
1456820-3	
1456821-1	
776437-3	
2320915-2	
1456820-2	
2320937-3	
2320918-2	
2320924-3	

Product Affected	Alias Part Number
776522-4	
1456823-2	
2320933-3	
776535-3	
1456821-3	
2320929-1	
2320934-3	
2320922-4	
776437-1	
776494-4	
2035367-3	
776487-3	
2035380-1	
776495-2	
2098555-1	
776523-1	
776524-2	
776487-2	
2035380-3	
2320926-3	
776488-1	"8202613276"
776523-2	
2320917-4	
2320932-3	
2035380-4	
776438-3	
1456820-4	
2035369-4	
776522-2	
776434-2	
776534-2	
776428-2	"820P-37520"
776434-3	
2320924-1	
776533-2	
776488-2	
2098556-4	
2320916-1	
776522-3	
2035559-2	

Product Affected	Alias Part Number
2320936-2	
776533-4	
1456821-2	
2035370-4	
2320926-2	
776494-3	
776538-3	
2320921-3	
2098242-2	
776524-1	"EG9731-000", "AMP-0-0776524-1"
776487-1	"8202613540"
2035559-1	
2320918-1	
776487-4	
776539-1	
776438-1	
776536-2	
1456823-3	
776535-2	
2035378-2	
2320915-3	
2035379-1	
2035559-3	
2320925-4	
2320934-2	
2320935-3	
776523-4	
2035380-2	
2320936-1	
2320920-1	
776532-4	
2098555-4	
2035379-4	
2320913-2	
2035367-4	
776532-2	
2035370-3	
2320922-1	
776532-1	
776531-2	

Product Affected	Alias Part Number
2098555-2	
2098238-2	
776539-4	
776533-3	
2035560-1	
2320923-2	
2320926-1	
776531-1	
776495-4	
776536-1	
2320933-4	
2320925-3	
2035561-1	
2035367-1	
776538-4	
776428-1	"820P-37461"
2320929-2	
2320914-2	
776488-4	
776429-4	
2098556-3	
2098553-4	
2320935-1	
2035562-4	
776539-3	
2320914-1	
2320917-2	
1456820-1	
2320930-3	
2320936-4	
2320922-2	
2320921-4	
776430-2	
2035559-4	
2035560-2	
2035381-2	
2320932-4	
2098237-2	
1456822-1	
2035560-3	

Product Affected	Alias Part Number
776523-3	
2320914-4	
2098554-2	
2035562-3	
776537-2	
2320920-3	
2320916-2	
2320918-3	
2035562-2	
776488-3	
776533-1	
2035378-1	
2320917-1	
776437-4	
2035561-4	
1456822-4	
2098242-1	
2320925-1	
2320937-1	
776538-1	
2320931-4	
2320922-3	
776534-4	"8202612469"
776438-4	
776433-2	
2098242-3	
776430-3	
2035369-1	
2035378-3	
2320937-4	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.