



17-Jun-2021

PCN #:PCN-21-105176

Subject:MOD II HR/VR RECPT. ASSY

Description of Change: Resin change for the housing from existing PA66 grade to a readily available PA66 grade. No effect on functionality. Parts have been validated see attached test report

Reason: Product Improvement. Discontinuance of currently used PA66 grade globally

Key Dates:

Contact By Date:21-Aug-2021

Implementation Date:21-Aug-2021

Product Affected	Alias Part Number
------------------	-------------------

8-534206-5	
------------	--

9-534206-0	
------------	--

4-535512-6	
------------	--

3-535512-7	
------------	--

1-535512-3	
------------	--

5-535542-5	
------------	--

535512-5	
----------	--

1-535512-0	
------------	--

2-535512-3	
------------	--

5-87879-2	
-----------	--

9-534206-1	
------------	--

7-535542-7	
------------	--

6-534206-9	
------------	--

8-535542-7	
------------	--

4-535512-8	
------------	--

7-535542-5	
------------	--

Product Affected	Alias Part Number
------------------	-------------------

6-535542-9	
5-535542-4	
8-534206-2	
535512-8	
5-87879-3	
8-534206-7	
5-535512-7	
7-535542-1	
3-535512-3	
6-535512-2	
6-535512-4	
5-535542-3	
4-535512-0	
2-1017008-9	
6-534206-3	
8-535542-2	
2-535512-9	
1-535512-1	
7-534206-6	
4-535512-3	
7-534206-7	
5-534206-1	
6-535512-1	
6-535542-6	
1-535512-6	
8-534206-1	
7-535542-0	
8-534206-0	
5-535512-0	
5-534206-2	
8-535542-8	
7-535542-8	
6-535512-0	
4-535512-9	
5-534206-5	
1017008-6	
7-535542-6	
3-535512-1	
4-535512-1	
5-535542-2	

Product Affected	Alias Part Number
6-535542-4	
2-535512-1	
5-535512-6	
3-535512-5	
5-535966-1	
8-535542-5	
8-535542-4	
6-534206-5	
8-87879-7	
5-535542-7	
6-534206-1	
1-535512-9	
6-534206-4	
6-534206-0	
5-87879-8	
8-535542-1	
6-87879-9	
8-535542-0	
8-534206-3	
3-535512-4	
2-535512-5	
5-534206-7	
6-535542-8	
7-534206-1	
1-535512-2	
1-535512-4	
5-535512-2	
6-534206-2	
7-534206-2	
535512-3	"2-29763-1024"
6-535512-3	"010-0945-00"
5-535542-8	
5-534206-3	
6-535542-1	
5-535512-9	
6-535542-3	
6-535542-0	
4-535512-4	
3-535512-8	
535512-7	

Product Affected	Alias Part Number
2-535512-6	
9-535542-0	
8-87879-1	
2-535512-4	
535512-1	
535512-2	"2-29763-0020"
8-535542-9	
6-534206-8	
7-535542-3	
7-534206-3	
6-535542-7	
6-534206-6	
7-534206-5	
8-534206-6	
535512-9	
5-535512-1	
5-534206-9	
6-535542-2	
535512-4	
5-534206-6	
3-535512-2	
3-535512-6	
7-534206-8	
3-535512-0	
535512-6	
7-534206-0	
7-535542-2	
5-535542-9	
1-535512-5	
1-535512-7	
1-535512-8	
8-534206-9	
5-535512-8	
5-535542-1	
8-534206-4	
7-534206-9	
5-535512-4	
2-535512-7	
6-535542-5	
7-535542-4	

Product Affected	Alias Part Number
5-535542-6	
5-534206-4	
5-535512-5	
8-534206-8	
5-534206-8	"010-5110-01"
2-535512-0	
2-535512-2	
7-535542-9	
8-535542-6	
6-534206-7	
535593-1	
2-535512-8	
5-535512-3	
4-535512-2	
7-534206-4	
4-535512-7	
8-535542-3	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.