

## PRODUCT CHANGE NOTIFICATION

Product Category GROUNDING PRODUCTS **20210604-02**

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE:  **IN**  **EMEA**  **LATAM**  **AP Jun-21**

IMPACTED REGIONS:  **DISCONTINUATION**

REASON FOR CHANGE:  **OTHER**

### DESCRIPTION OF CHANGE: (Required)

Some grounding connectors will be discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

### DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2021	10	6

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

### CUSTOMER SERVICE CONTACTS

<b>ASIA PACIFIC</b>	AUSTRALIA: 1-800 7263848 <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	CHINA: 400-820-1900 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	HONG KONG: 800-965768 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile)	INDONESIA: 001 803 65 7571	JAPAN: +81-3-6863-6000

	<a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>
	<b>TAIWAN: 0080 165 1487</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
<b>LATIN AMERICA</b>	<b>BRAZIL 08000562613 (Toll Free)</b> <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520</b> <b>01 800 360 86 00 (Toll Free)</b> <a href="mailto:MEX-customerservice@panduit.com">MEX-customerservice@panduit.com</a>	<b>OTHER LA COUNTRIES:</b> <b>Phone USA 1-708-532-1800</b> <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	<b>EMEA: +44 208 6017219</b> <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>

IMPACTED PART NUMBER(S)	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
GCC6X61/0-1/0	Compatible	GCC6-250-250			6-Oct-2021
GCC6X6500-1/0	Compatible	GCC6-500-250			6-Oct-2021
GCHE250-250	Compatible	GCE250-250			6-Oct-2021
GCHE500-250	Compatible	GCE500-250			6-Oct-2021
GH-1-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
GH-2-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
GH-5-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GH-6-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GJ1000-58-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GJ2/0-38-5	No Replacement	NO-REPLACEMENT			6-Oct-2021
GJ250-12-3	No Replacement	NO-REPLACEMENT			6-Oct-2021
GJ4-38-5	No Replacement	NO-REPLACEMENT			6-Oct-2021
GJ500-12-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GJ750-58-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPC4H250-2	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-15-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-20-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-21-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-45-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-51-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-52-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-75-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-76-1	No Replacement	NO-REPLACEMENT			6-Oct-2021
GPL-9-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
GRC1/0-34X-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
GRC3/0-34-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
GSP1-10-4-C	Compatible	SP1-4L-C			6-Oct-2021
GSP1-4-2/0-L	Compatible	SP1-2/0-Q			6-Oct-2021
GSP2-10-4-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
GSP2-12-6-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
GU-13-3	No Replacement	NO-REPLACEMENT			6-Oct-2021
GUBC500-6TP	Compatible	GUBC500-6			6-Oct-2021
LCC1/0-12-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021

LCC2/0-12-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCC2-12-B-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCC250-12-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCC500-12-B-6	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCC6-12-B-L	No Replacement	NO-REPLACEMENT			6-Oct-2021
LIAS1/0-14-L	Compatible	LIAS250-56-Q			6-Oct-2021
MGC2-2/0-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
MGC2-250-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
MGC2-4-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
MGC2-500-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
SDR50	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-1/0-L	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-1/0L-L	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-2/0L-Q	Compatible	SP1-2/0-Q			6-Oct-2021
SP1-2/0-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-2-C	Compatible	GSP1-6-2-C			6-Oct-2021
SP1-2L-C	Compatible	GSP1-6-2-C			6-Oct-2021
SP1-350-12	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-350L-12	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-3-C	Compatible	GSP1-6-2-C			6-Oct-2021
SP1-3L-C	Compatible	GSP1-6-2-C			6-Oct-2021
SP1-4/0L-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-4/0-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-4-C	Compatible	SP1-4L-C			6-Oct-2021
SP1-500-12	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-500L-12	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP1-7-C	Compatible	GSP1-12-6-C			6-Oct-2021
SP1-7L-C	Compatible	GSP1-12-6-C			6-Oct-2021
SP1-8-C	Compatible	GSP1-12-6-C			6-Oct-2021
SP1-8L-C	Compatible	GSP1-12-6-C			6-Oct-2021
SP2-1/0-L	Compatible	GSP2-2-2/0-L			6-Oct-2021
SP2-1/0L-L	Compatible	GSP2-2-2/0-L			6-Oct-2021
SP2-350-12	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP2-350L-12	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP2-3-C	Compatible	GSP2-10-2-C			6-Oct-2021
SP2-3L-C	Compatible	GSP2-10-2-C			6-Oct-2021
SP2-4/0L-Q	Compatible	SP2-4/0-Q			6-Oct-2021
SP2-4-C	Compatible	GSP2-10-2-C			6-Oct-2021
SP2-4L-C	Compatible	GSP2-10-2-C			6-Oct-2021
SP2-500-12	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP2-500L-12	No Replacement	NO-REPLACEMENT			6-Oct-2021
SP2-7-C	Compatible	GSP2-12-6-C			6-Oct-2021
SP2-7L-C	Compatible	GSP2-12-6-C			6-Oct-2021
SP2-8-C	Compatible	GSP2-12-6-C			6-Oct-2021
SP2-8L-C	Compatible	GSP2-12-6-C			6-Oct-2021

SPF1-4-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SPF2-3-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SSCW14-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SSCW38-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SSFW14-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SSFW38-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SSN1420-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SSN3816-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SSNTS1420-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
SSNTS3816-C	No Replacement	NO-REPLACEMENT			6-Oct-2021
TGCE250	No Replacement	NO-REPLACEMENT			6-Oct-2021
WB12-L	No Replacement	NO-REPLACEMENT			6-Oct-2021
WB34-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
WB58-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
SCST1/0-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
SCST2/0-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
SCST250-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
SCST2-B-Q	No Replacement	NO-REPLACEMENT			6-Oct-2021
SCST3/0-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
SCST350-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
SCST4/0-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
SCST500-B-6	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCDT2/0-12-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCDT250-12-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCDT3/0-12-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCDT350-12-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCDT4/0-12-B-X	No Replacement	NO-REPLACEMENT			6-Oct-2021
LCDT500-12-B-6	No Replacement	NO-REPLACEMENT			6-Oct-2021