

Product Change Notification

Product Affected

MC21605H6W-FPTLW3.3-V2 – 3678761

Change Rationale

Part of BOM for ARM.

What has changed

Added pin header based on 3398598. All 3678761 parts will now be supplied with a soldered pin header as per the picture below.



Effective date

Immediately.