

ERRATA

N° 10261AERRA

Dear customer,

With this Infineon Technologies AG errata note we would like to inform you about the following

Correction of configurable parameters, tolerance classes, and electrical characteristics




On 16 April 2020, Infineon acquired Cypress.
We are now in the process of merging and consolidating our tools and processes for PCN, Information Notes, Errata and Product Discontinuance.
For further details, please visit our website:
<https://www.infineon.com/cms/en/about-infineon/company/cypress-acquisition/>

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Constanze Hufenbecher, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

ERRATA

N° 10261AERRA

▶ **Products affected** Please refer to attached affected product list 1_cip10261 

▶ **Detailed change information**

Subject New datasheet version V1.2

Reason Update of datasheet from version V1.1 to V1.2

Description	<u>Old</u>	<u>New</u>
	■ 1.1	■ 1.2

▶ **Impact of change** Assessment in application is recommended. For new system designs the new datasheet should be used.

▶ **Attachments**

1_cip10261	affected product list
3_cip10261	published datasheet

▶ **Implementation date** 2021-06-02

If you have any questions, please do not hesitate to contact your local sales office.