

Product Change Notification

Current Date: 18-Nov-2021

TE Connectivity

Product Change Notification: P-21-021743

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

PCN Date: 17-NOV-21

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: LKZ and ESSW labels

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from TE Connectivity R dermark, Germany manufacturing location to TE Connectivity Grenoble France manufacturing location.

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance. Country of origin will be updated once transfer is complete

Estimated Dates:					
Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):					
	20-MAY-2022				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	No Mixed Shipments				

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>6-1768034-2</u>	NO			"D98384-000", "LKZ12B4"			
<u>6-1768034-3</u>	NO			"E52261-000", "LKZ12B5"			
<u>7-1768019-9</u>	NO			"C43336-000", "ESSW1-025"			
<u>7-1768034-8</u>	NO			"F69457-000", "LBGLKZ16B4"			
<u>8-1768034-0</u>	NO			"F73855-000", "LKZ16B6"			
<u>C56426-000</u>	NO			"7-1200860-4", "LKZ12B3"			

Customer: TTI, Inc. (1305175) Part Number(s) being Modified: Location: Maisach-gernlinden

Agreement Number: TTI001

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>6-</u> 1768034- 2	NO		TYC6-1768034-2	"D98384-000", "LKZ12B4"			
<u>6-</u> 1768034- <u>3</u>	NO		TYC6-1768034-3	"E52261-000", "LKZ12B5"			
<u>7-</u> 1768019- <u>9</u>	NO		TYC7-1768019-9	"C43336-000", "ESSW1-025"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>7-</u> 1768034- 8	NO		TYC7-1768034-8	"F69457-000", "LBGLKZ16B4"			
<u>8-</u> 1768034- 0	NO		8-1768034-0	"F73855-000", "LKZ16B6"			
<u>C56426-</u> 000	NO		,	"7-1200860-4", "LKZ12B3"			

Customer: TTI, Inc. (3057778) Part Number(s) being Modified: Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>6-</u> 1768034- 2	NO		TYC6-1768034-2	"D98384-000", "LKZ12B4"			
<u>6-</u> 1768034- <u>3</u>	NO		TYC6-1768034-3	"E52261-000", "LKZ12B5"			
<u>7-</u> 1768019- 9	NO		TYC7-1768019-9	"C43336-000", "ESSW1-025"			
<u>7-</u> 1768034- 8	NO		TYC7-1768034-8	"F69457-000", "LBGLKZ16B4"			
<u>8-</u> 1768034- 0	NO		8-1768034-0	"F73855-000", "LKZ16B6"			
<u>C56426-</u> 000	NO		TYCC56426-000, RAYC56426-000	"7-1200860-4", "LKZ12B3"			