

Honeywell Announces Obsolescence and Last-Time Buy Opportunity for Certain Basic Switches Part Numbers

Honeywell is announcing an opportunity to place a last-time buy order in relation to 552 Basic Switches part numbers. This announcement relates only to the part numbers specified below; it does not represent a full discontinuation of the product lines into which such part numbers are grouped.

We apologize for any delays in shipments on Large Basics Switches and have been analyzing ways to improve productivity. This analysis has uncovered a large number of rarely, infrequently used parts that complicate our supply chain. Our plan is to simplify our offering and improve our cycle time through reducing those infrequent SKUs. This notification will allow you to purchase such SKUs one last time. For customers with any special requirements, we can look at alternatives in the portfolio to suit your application.

Due to a fixed amount of remaining capacity, fulfillment of last-time buy orders will be limited and subject to cancellation at any time. It is recommended that orders be placed promptly to improve the likelihood of fulfillment. Please refer to the Timeline of Events shown below for more details.

AFFECTED PART NUMBERS

This announcement serves as the formal communication that the SKUs listed below will no longer be available for sale in accordance with the Timeline of Events shown below.

Obsoleted Part Numbers with Last-time Buy Option			
BZ-RX6672-F1	BZ-R7216-P5	BZ-7R-P5	BZ-2RW843589-P4
BZ-RX53-B7	BZ-R7216=CCS	BZ-7RL367T	BZ-2RW8435109-P4
BZ-RX47	BZ-R55-S	BZ-7RL127	BZ-2RW843311
BZ-RX243	BZ-R55-P4-S=BC	BZ-7RD-A2	BZ-2RW8422-A2
BZ-RX20=SOR	BZ-R55-A2-S	BZ-7R-A2N131	BZ-2RW84203-A2
BZ-RX20	BZ-R55514-P4	BZ-7R-A2N130	BZ-2RW84118-A41
BZ-RX122-A29	BZ-R55511-A4	BZ-7R55T-S	BZ-2RW84
BZ-RX	BZ-R370-P5	BZ-7R336T	BZ-2RW82T
BZ-RW-F1	BZ-R309-A2=TPI	BZ-7R277=SOR1	BZ-2RW82-A2N131
BZ-RW85X2	BZ-R2439-P4	BZ-7R24-A2	BZ-2RW82-A2=ICI
BZ-RW84-N94	BZ-R2430-P1=SOR	BZ-5RW84-A2N161	BZ-2RW8292
BZ-RW84461-A2	BZ-R2136-P1=SOR	BZ-3YWT822	BZ-2RW82725551-D6
BZ-RW84411-A2	BZ-R19-A2	BZ-3YQ69T	BZ-2RW8255T-S
BZ-RW843585-A22	BZ-R186	BZ-3YQ66T	BZ-2RW8255-A2
BZ-RW8435161-A2	BZ-R179-WFDE-240	BZ-3YQ18T	BZ-2RW825551-D6=KW
BZ-RW843515	BZ-R179-WFDE-060-T	BZ-3YDT	BZ-2RW8244-P4
BZ-RW8435052-A2	BZ-R179-WCBA-240	BZ-3RW8995519-PC2	BZ-2RW8244-A2=SOR
BZ-RW8435051-D6	BZ-R179-WCBA-060-T	BZ-3RW825515-A2-S	BZ-2RW82444-A2
BZ-RW8435	BZ-R178-WFDE-240	BZ-3RW822T	BZ-2RW82443-A2
BZ-RW8422-P4	BZ-R178-WFDE-050-T	BZ-3RW822158-A46=C	BZ-2RW8238-A2
BZ-RW8422-A2	BZ-R178-WCBA-240	BZ-3RW8221555513T-S	BZ-2RW822-P4
BZ-RW842214-P5	BZ-R178-WCBA-060-T	BZ-3RW8221555513T	BZ-2RW822-D612
BZ-RW84052-D6	BZ-R173-P4	BZ-3RW82134-A2	BZ-2RW822-A2N142

BZ-RW82051-A2	BZ-R173-A4	BZ-3RW8055-A2-S	BZ-2RW82291-A2
BZ-RW80X33-D5	BZ-R169-WCBA-060-T	BZ-3RW80552-A2-S	BZ-2RW82279-A21
BZ-RW80-A2N156	BZ-R169-P5	BZ-3RW80551-A2-S	BZ-2RW82276T
BZ-RS	BZ-R1692	BZ-3RQ115T	BZ-2RW822725551-A2
BZ-RQX167	BZ-R1691	BZ-3RDS15T-S	BZ-2RW82271
BZ-RQX	BZ-R05323=TPI	BZ-3RDS152T-S	BZ-2RW8225-A2-S
BZ-RQ66	BZC-2RW876T	BZ-3R291-P4=SOR	BZ-2RW82255T-S
BZ-RQ1T04	BZC-2RW82-A2	BZ-3R291-P1	BZ-2RW82255-S
BZ-R-P4	BZC-2RQ181-A2	BZ-3R	BZ-2RW82255-A2-S=N
BZ-R-N111	BZC-2RD-A2	BZ-3AW82254T	BZ-2RW82255721W122
BZ-RMX6-B7	BZC-2R-A2	BZ-3AW8055511T	BZ-2RW8225551-D6
BZ-RMX4-A29	BZ-7YQ1T1	BZ-3AT	BZ-2RW822555117-A2
BZ-RD-A2N6	BZ-7RX-N2	BZ-3ALT1	BZ2RW822555114W116
BZ-RD-A2N10	BZ-7RW84-A2	BZ-3AD-PC2=BC	BZ-2RW8225534-W123
BZ-RD-A2	BZ7RW82550511PC2S=	BZ-3A55T	BZ-2RW8222-A2
BZ-RD24-A4	BZ-7RW822-A2	BZ-2RW896-A2=NEW	BZ-2RW8219-A2
BZ-RD242	BZ-7RW82137T-S	BZ-2RW876-PC2	BZ-2RW82128-T
BZ-RD	BZ-7RW82135-A2	BZ-2RW863T	BZ-2RW82120-A21
BZ-R-A2N110	BZ-7RW82132T-S=ICI	BZ-2RW8635551-A2	BZ-2RW82113T
BZ-R-A2N104	BZ-7RW8055151-A2-S	BZ-2RW863	BZ-2RW82
BZ-R-A2=UEC	BZ-7RW2T04	BZ-2RW855T-S	BZ-2RW80-A2UL
BZ-R88-A2	BZ-7RT-N119	BZ-2RW855-A2-S	BZ-2RW8072-A2=SOR
BZ-R814=UEC	BZ-7RT04	BZ-2RW855511T	BZ-2RW8055513T=CA2
BZ-R812	BZ-7RST	BZ-2RW8497-A2	BZ-2RW80290
BZ-R7223312-P1=SOR	BZ-7RQ18T	BZ-2RW8472516-A2	BZ-2RW8024
BZ-R72219-A2	BZ-7RQ181T	BZ-2RW84462-A2	BZ-2RW80233-A2=FWM
BZ-R72219=UEC2	BZ-7RQ144T	BZ-2RW8435-A2	BZ-2RW80172-A2=FWM
BZ-2RW80172-A2	BZ-2RM2-A2	BZ-2R244T	YA-2RL-A6
BZ-2RW80161-A2	BZ-2RM22-A2	BZ-2R244-P1	YA-2RBT
BZ-2RW53-A2RS	BZ-2RM22	BZ-2R244-A2	YA-2RB-D504
BZ-2RT	BZ-2RM2	BZ-2R168-A2=FWM	YA-2RB-A64
BZ-2RS-P1	BZ-2RL-P4	BZ-2R=SAG	YA-2RB18-A21
BZ-2RS72-A2	BZ-2RL-A2	BZ-2G-A2	YA-2R-A2
BZ-2RS5551-A2	BZ-2RL712	BZ-2AW855T1	XS15279
BZ-2RQW15-D6	BZ-2RL711	BZ-2AW8424493TSB	WZ-2RW82255223T-S
BZ-2RQ-A2N11	BZ-2RL5551T	BZ-2AW842444T	WZ-2RW8225515T-S
BZ-2RQ77-N23	BZ-2RL5551-A2	BZ-2AW84223T	WZ-2RQ1846
BZ-2RQ722-A2	BZ-2RL2T04	BZ-2AW82T	WZ-2RQ15-A2
BZ-2RQ722233-A2=DT	BZ-2RL2	BZ-2AW825551T	WZ-2R268-D6
BZ-2RQ66-N26	BZ-2RL	BZ-2AQ784T	WM-1R369-AR4
BZ-2RQ25272T	BZ-2RD-WFDE-240	BZ-2AQ1T	WA-2R98-A4
BZ-2RQ24-A2	BZ-2RDT	BZ-2AQ1842-PC2	WA-2R202-A73
BZ-2RQ241-D5	BZ-2RDST-S	BZ-2ADT1	WA-2R177-A41
BZ-2RQ239-A2	BZ-2RDS-A2	BZ-1RD-A2N5	WA-1RX-A4
BZ-2RQ232-A2	BZ-2RDS725551-A2	BZ-1R374-P4	WA-1RX12-A41
BZ-2RQ1-P4	BZ-2RDS24-S	BZ-1R2447-P4=SOR	WA-1RVX12572-A4
BZ-2RQ1-D682	BZ-2RDS	YZ-RX-D584	WA-1RVX051-A4

BZ-2RQ1-A2=NEW	BZ-2RD-P4	YZ-RWT5551152	SLP-A
BZ-2RQ18T=NEW	BZ-2RD-D82	YZ-RW8435722054-D6	SL-P1
BZ-2RQ18-P4	BZ-2RD-A2N11	YZ-RW8435052-D6	SL-P
BZ-2RQ18M-A2	BZ-2RD72-A2	YZ-RW8435052-A2	SL-H
BZ-2RQ18-D5	BZ-2R-D5	YZ-RSX351	SL-F
BZ-2RQ1824-A2	BZ-2RD44-PC2	YZ-R	SL-E1
BZ-2RQ181	BZ-2RD42-P4	YZ7RW8221555516T=W	SL-B
BZ-2RQ18	BZ-2RD331	YZ-2RW84-A2	SL-A
BZ-2RQ175-A2	BZ-2R-A2N94	YZ-2RW84510-A2	SCN-2623SC
BZ-2RQ174-A2	BZ-2R-A2N80	YZ2RW8435114D5S=UT	SCN-2603SC
BZ-2RQ1725-D6=VT	BZ-2R-A2N100	YZ2RW82725551D6=KW	SCN-2417SC
BZ-2RQ17223536-D6	BZ-2R-A22F1	YZ-2RW827255518-D6	SCN-2414SC
BZ-2RQ13-A2	BZ-2R72-A2=SAG	YZ-2RW812-A2	SCN-2209SC
BZ-2RQ1331	BZ-2R725551-A2	YZ-2RW805551T	SCN-2202SC
BZ-2RQ128T	BZ-2R708-P7	YZ-2RW130-D6	SCN-1636SC
BZ-2RQ124-D6=JBC	BZ-2R55-A2	YZ-2RS-A2	SCN-1628SC
BZ-2RQ115-A2	BZ-2R5551-P4	YZ-2RQW12-W120	PA10063
BZ-2RQ1020-A2	BZ-2R55513-A2	YZ-2RQ1T	MT-4RV-A28=SOR
BZ-2RQ1016-W119=AP	BZ-2R55	YZ-2RQ172-W105=VT	MT-4RV36-D73
BZ-2RQ1015-W109=DT	BZ-2R383-A2	YZ-2RDS5551-D6	MT-4RV34-A28
BZ-2RQ	BZ-2R352420-A2	YZ-2RDS5551-A22	MT-4RV22
BZ-2R-P5=BC3	BZ-2R331	YZ-2RDS555116-D6-S	MT-4R-P1
BZ-2R-P1	BZ-2R291-P4=SOR	YZ-2RDS42	MT-4RL2-A28
BZ-2R-N87	BZ-2R291-A4	YM-1R2450=INV	MT-4RL2
BZ-2RN7T	BZ-2R276-P5	YE-2RV22-D5	MT-4R-A210
BZ-2RN784	BZ-2R258=CCS	YE-2RV198-A41=KNG	MT-4R27=UEC7
BZ-2RN770	BZ-2R258	YE-2RV198-A41	MT-4R
BZ-2RN730	BZ-2R24-A2N84	YE-2RQ27-A4	12BS217=UEC
BZ-2R-N114	BZ-2R24-A2=AVM1	YA-2RQ18248-D6	12BS214
BZ-2RM-A2	BZ-2R24-A2=AVM	YA-2RQ1243-D6	12BS211
MDA3711Q	BF-10030	AS-12031	12BS201
MD3211Q16	BE-R0512-D69	AS-10043	10BS226
MD3211Q	BE-R0512-A2=RSC3	ADD3721R	10BS217
MD2721	BE-2RV-A2	ADD1721R21	10BS212
MCD2711H	BE-2RL-A4	8AS264-MT	1022710
MCA2711H	BE-2RB232-A4	8AS244-MT	1022688
MCA2711	BE-2RB	6BS1-B	1022686
MC2711=MCI	BE-2R279	6AS-N39	1022682
MBH2731	BE-2R25-A4	6AS5	1022681
LS-20329	BE-2R2425	5PA3	1022680
JS-151=MAH	BE-2R143	5PA2-RS	1022432
JS-151=HON194	BE-1RV52-A4	5PA2=FWM	10-22139
JR	BE-1RV320-A4	50015033	10-22018
G-RLX	BA-RV22351-D688	50011683	10-21931
DTE7-2RN-PG	BA-5RV310-A2	41TB5-3	10-21721
DT-2RV-B6	BA-3ST=LSC10	3TB41-15	1021539
DT-2RV212-A7=AVM	BA-3RX717	3TB1-15	10-19761

DT-2RS1-A7	BA-2SBT	32339479-001	
DT-2R711-A7	BA-2RV338	2MN9	
DT-2R4-B6	BA-2RV32-P405=LSC4	2MN8	
DT-2R4-A7	BA-2RV32-P405	2MN6	
DT-2R3-A7	BA-2RV312T	2MN24-N5	
DT-10309	BA-2RV303	2MN11	
DT-10306	BA-2RV22T	2E1	
DT10302	BA-2RV22-D6	1TB28-2	
DT-10221	BA-2RV2223-A2	1TB242-4	
DT-10214	BA-2RV136-A2	1TB1-2=NEW	
DT-10167	BA-2RQ1T	1AC24	
DT-10165	BA-2R-P4	1018744SC	
BM-2R559729-A4	BA-2R-P1	10-18644	
BM-1RW82-A2	BA-2RL-A2	10-17307	
BM-1RW822-A2	BA-2RL2-A2	10-17306	
BM-1RS-A2	BA-2RB-A4	10-15769	
BM-1RQ1-A2	BA-2RB7-P4	10-15235=TEC	
BM-1R-P5	BA-2RB35-A2	10-15057	
BM-1RD33-A2=AVM	BA-2RB	1012533	
BM-1R-A4	BA-2R-A4	0954850	
BM-1R-A2	BA-2R708-P7	0952493	
BM-1R392-A2	BA-2R62-P5	0951895	
BM-1R373	BA-2R62-A2=LSC2	0951703	
BM-1R369-A41	BA-2R24-A2	0951702	
BM-1R332-A2=TPI	BA-2R	0950700	
BM-1R2451-A2	BA-2CB708-A2		
BM-1R2420=UEC2	BA-1RV5435247-A2		
BM-1R2420	BA-1RV5435241-A2		
	BA-1RV54352411-A21		
	BA-1R543524-A2		
	BA-1R3511		

TIMELINE OF EVENTS

The following timeline pertains to all affected SKUs. These dates are subject to change based on availability.

Action	Description	Date
Last-Time Buy	Request price quote for option #1 window.	Now to December 31, 2021
Last Ship Date for LTB Orders	Depending upon factory loading, Honeywell will contact customers to recommend delivery dates.	Now to June 31, 2022

REGIONS AFFECTED

- Asia Pacific (APAC)
- Europe, Middle East, Africa (EMEA)
- Greater China (GrCH)
- Latin America (LATAM)
- North America (NA)

CONTACT INFORMATION

Honeywell is committed to providing you with a superior level of customer service. Please contact your Honeywell representative for additional information regarding this communication.

- **Product marketing:**
 - North America: Pam Davis, Sr. Customer Marketing Specialist, pam.davis@honeywell.com
 - EMEA: Stephanie Edmonson, Sr Customer Marketing Specialist, stephanie.edmonson@honeywell.com
 - China: Jian Zou, Sr. Customer Marketing Manager, jian.zou@honeywell.com
 - MERTA: Lalehan Candemir, Sr. Customer Marketing Manager, lalehan.candemir@honeywell.com
 - India: Jeevesh, Bawa, Sr. Customer Marketing Manager, Jeevesh.Bawa@Honeywell.com

- **Application engineering:**
 - Global: Darryl Ballard, Advanced Application Engineer, darryl.ballard@honeywell.com

WARRANTY/REMEDY

Subject to the following conditions, Honeywell warrants goods of its manufacture as being free of defective materials and faulty workmanship during the applicable warranty period. Honeywell's standard product warranty applies unless agreed to otherwise by Honeywell in writing; please refer to your order acknowledgement or consult your local sales office for specific warranty details. If warranted goods are returned to Honeywell during the period of coverage, Honeywell will repair or replace, at its option, without charge those items that Honeywell, in its sole discretion, finds defective. **Notwithstanding the foregoing, in the event of a product end-of-life or obsolescence, or inability of Honeywell to manufacture or source materials or component parts for a product, for whatever reason, and/or any associated last-time buy in relation to a product (an "Obsolescence"), Honeywell shall engage in commercially reasonable efforts to repair or replace products in accordance with the terms of its standard warranty, but in no event shall it be liable if it is unable to do so due to the Obsolescence. The foregoing is buyer's sole remedy and is in lieu of all other warranties, expressed or implied, including those of merchantability and fitness for a particular purpose. In no event shall Honeywell be liable for consequential, special, or indirect damages.**