

	SGP-Customer_Service@panduit.com	SGP-Customer_Service@panduit.com	JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
AFR4BCIW6	Compatible	AFR4BCBL6			8-Feb-22
AFR4CCIW	Compatible	AFR4CCBL			8-Feb-22
AFR4ECIW	Compatible	AFR4ECBL			8-Feb-22
AFR4JB2SIW	Compatible	AFR4JB2SBL			8-Feb-22
AFR4RAIW	Compatible	AFR4RABL			8-Feb-22
AFR4TRT70IW	Compatible	AFR4TRT70BL			8-Feb-22
AFR4WTRIW	Compatible	AFR4WTRBL			8-Feb-22
AFR4TBLGIW	Compatible	AFR4TBLGBL			8-Feb-22