



Product Change Notification

Current Date: 24-Jan-2022

TE Connectivity

Product Change Notification: P-22-022056

PCN Date: 21-JAN-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Mini CT/CT and EI series

Description of Changes
Package change, detail see attachment
Other attachments:
Packaging change for Mini CT/CT &EI series

Reason for Changes:
Product improvement.The Packaging change causing of the packaging process from manual weighting to automotive counting. A little change of package, detail see attachment.

| Estimated Dates: | |
|--|--|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 21-FEB-2022 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------|---------------------------|------------------|----------------------|------------------------|---------------------------------|---------------------------|
| <u>1-171825-0</u> | NO | | | | | |
| <u>1-171825-2</u> | NO | | | | | |
| <u>1-171826-0</u> | NO | | | | | |
| <u>1-171826-2</u> | NO | | | | | |
| <u>1-173977-0</u> | NO | | | | | |
| <u>1-173977-1</u> | NO | | | | | |
| <u>1-173977-2</u> | NO | | | | | |
| <u>1-173977-3</u> | NO | | | | | |
| <u>1-173977-4</u> | NO | | | | | |
| <u>1-173977-5</u> | NO | | | | | |
| <u>1-292161-0</u> | NO | | | | | |
| <u>1-292161-1</u> | NO | | | | | |
| <u>1-292161-2</u> | NO | | | | | |
| <u>1-292161-3</u> | NO | | | | | |
| <u>1-292161-4</u> | NO | | | | | |
| <u>1-292161-5</u> | NO | | | | | |
| <u>1-292215-0</u> | NO | | | | | |
| <u>1-292215-1</u> | NO | | | | | |
| <u>1-292215-2</u> | NO | | | | | |
| <u>1-292215-3</u> | NO | | | | | |
| <u>1-292215-4</u> | NO | | | | | |
| <u>1-292215-5</u> | NO | | | | | |
| <u>1-292215-6</u> | NO | | | | | |
| <u>1-292215-7</u> | NO | | | | | |
| <u>1-292215-8</u> | NO | | | | | |
| <u>1-292215-9</u> | NO | | | | | |
| <u>1-292253-0</u> | NO | | | | | |
| <u>1-292253-1</u> | NO | | | | | |
| <u>1-292253-2</u> | NO | | | | | |
| <u>1-292253-3</u> | NO | | | | | |
| <u>1-292253-4</u> | NO | | | | | |
| <u>1-292253-5</u> | NO | | | | | |
| <u>1-292271-0</u> | NO | | | | | |
| <u>1-353293-0</u> | NO | | | | | |
| <u>1-353293-1</u> | NO | | | | | |
| <u>1-353293-2</u> | NO | | | | | |
| <u>1-353293-3</u> | NO | | | | | |
| <u>1-353293-4</u> | NO | | | | | |
| <u>1-353293-5</u> | NO | | | | | |
| <u>1-353293-6</u> | NO | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------|---------------------------|------------------|----------------------|------------------------|---------------------------------|---------------------------|
| <u>1-353293-7</u> | NO | | | | | |
| <u>1-353293-8</u> | NO | | | | | |
| <u>1-353293-9</u> | NO | | | | | |
| <u>171825-2</u> | NO | | | | | |
| <u>171825-3</u> | NO | | | | | |
| <u>171825-4</u> | NO | | | | | |
| <u>171825-5</u> | NO | | | | | |
| <u>171825-6</u> | NO | | | | | |
| <u>171825-7</u> | NO | | | | | |
| <u>171825-8</u> | NO | | | | | |
| <u>171825-9</u> | NO | | | | | |
| <u>171826-2</u> | NO | | | | | |
| <u>171826-3</u> | NO | | | | | |
| <u>171826-4</u> | NO | | | | | |
| <u>171826-5</u> | NO | | | | | |
| <u>171826-6</u> | NO | | | | | |
| <u>171826-7</u> | NO | | | | | |
| <u>171826-8</u> | NO | | | | | |
| <u>171826-9</u> | NO | | | | | |
| <u>172107-2</u> | NO | | | | | |
| <u>172107-4</u> | NO | | | | | |
| <u>173977-2</u> | NO | | "200058", "15-0167" | | | |
| <u>173977-3</u> | NO | | | | | |
| <u>173977-4</u> | NO | | | | | |
| <u>173977-5</u> | NO | | "0-0173977-5" | | | |
| <u>173977-6</u> | NO | | | | | |
| <u>173977-7</u> | NO | | | | | |
| <u>173977-8</u> | NO | | | | | |
| <u>173977-9</u> | NO | | | | | |
| <u>176153-2</u> | NO | | | | | |
| <u>176153-3</u> | NO | | | | | |
| <u>176153-4</u> | NO | | | | | |
| <u>176153-5</u> | NO | | | | | |
| <u>176153-6</u> | NO | | | | | |
| <u>176392-6</u> | NO | | | | | |
| <u>1932811-3</u> | NO | | | | | |
| <u>2-171825-2</u> | NO | | | | | |
| <u>2-171825-3</u> | NO | | | | | |
| <u>2-171825-4</u> | NO | | | | | |
| <u>2-173977-2</u> | NO | | | | | |
| <u>2-173977-3</u> | NO | | | | | |
| <u>2-173977-4</u> | NO | | | | | |
| <u>2-173977-5</u> | NO | | | | | |
| <u>2-173977-6</u> | NO | | | | | |
| <u>2-173977-7</u> | NO | | | | | |
| <u>2-173977-8</u> | NO | | | | | |
| <u>2-173977-9</u> | NO | | | | | |
| <u>2-179694-2</u> | NO | | | | | |
| <u>2-179694-3</u> | NO | | | | | |
| <u>2-179694-4</u> | NO | | | | | |
| <u>2-179694-5</u> | NO | | | | | |
| <u>2-179694-6</u> | NO | | | | | |
| <u>2-179694-7</u> | NO | | | | | |
| <u>2-179694-8</u> | NO | | | | | |
| <u>2-179694-9</u> | NO | | | | | |
| <u>2-292161-2</u> | NO | | | | | |
| <u>2-292161-3</u> | NO | | | | | |
| <u>2-292161-4</u> | NO | | | | | |
| <u>2-292161-5</u> | NO | | | | | |
| <u>2-292161-6</u> | NO | | | | | |
| <u>2-292161-7</u> | NO | | | | | |
| <u>2-292161-8</u> | NO | | | | | |
| <u>2-292161-9</u> | NO | | | | | |
| <u>2-292215-0</u> | NO | | | | | |
| <u>2-292215-4</u> | NO | | | | | |
| <u>2-292215-5</u> | NO | | | | | |
| <u>2-292215-6</u> | NO | | | | | |
| <u>2-292215-7</u> | NO | | | | | |
| <u>2-292215-8</u> | NO | | | | | |
| <u>2-292215-9</u> | NO | | | | | |
| <u>2-292216-2</u> | NO | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------|---------------------------|------------------|----------------------|------------------------|---------------------------------|---------------------------|
| <u>2-292216-4</u> | NO | | | | | |
| <u>2-292216-6</u> | NO | | | | | |
| <u>2-292216-8</u> | NO | | | | | |
| <u>2-292253-2</u> | NO | | | | | |
| <u>2-292253-3</u> | NO | | | | | |
| <u>2-292253-4</u> | NO | | | | | |
| <u>2-292253-6</u> | NO | | | | | |
| <u>2-353293-0</u> | NO | | | | | |
| <u>2-353293-2</u> | NO | | | | | |
| <u>2-353293-3</u> | NO | | | | | |
| <u>2-353293-4</u> | NO | | | | | |
| <u>2-353293-5</u> | NO | | | | | |
| <u>2-353293-6</u> | NO | | | | | |
| <u>2-353293-7</u> | NO | | | | | |
| <u>2-353293-8</u> | NO | | | | | |
| <u>2-353293-9</u> | NO | | | | | |
| <u>292145-3</u> | NO | | | | | |
| <u>292145-4</u> | NO | | | | | |
| <u>292145-5</u> | NO | | | | | |
| <u>292145-6</u> | NO | | | | | |
| <u>292161-2</u> | NO | | | | | |
| <u>292161-3</u> | NO | | | | | |
| <u>292161-4</u> | NO | | | | | |
| <u>292161-5</u> | NO | | | | | |
| <u>292161-6</u> | NO | | | | | |
| <u>292161-7</u> | NO | | | | | |
| <u>292161-8</u> | NO | | | | | |
| <u>292161-9</u> | NO | | | | | |
| <u>292215-3</u> | NO | | | | | |
| <u>292215-4</u> | NO | | | | | |
| <u>292215-5</u> | NO | | | | | |
| <u>292215-6</u> | NO | | | | | |
| <u>292215-7</u> | NO | | | | | |
| <u>292215-8</u> | NO | | | | | |
| <u>292215-9</u> | NO | | | | | |
| <u>292253-2</u> | NO | | | | | |
| <u>292253-3</u> | NO | | | | | |
| <u>292253-4</u> | NO | | | | | |
| <u>292253-5</u> | NO | | | | | |
| <u>292253-6</u> | NO | | | | | |
| <u>292253-7</u> | NO | | | | | |
| <u>292253-8</u> | NO | | | | | |
| <u>292253-9</u> | NO | | | | | |
| <u>292271-3</u> | NO | | | | | |
| <u>292271-4</u> | NO | | | | | |
| <u>292271-5</u> | NO | | | | | |
| <u>292389-3</u> | NO | | | | | |
| <u>3-173977-0</u> | NO | | | | | |
| <u>3-173977-1</u> | NO | | | | | |
| <u>3-173977-2</u> | NO | | | | | |
| <u>3-173977-3</u> | NO | | | | | |
| <u>3-173977-4</u> | NO | | | | | |
| <u>3-173977-5</u> | NO | | | | | |
| <u>3-179694-0</u> | NO | | | | | |
| <u>3-179694-1</u> | NO | | | | | |
| <u>3-179694-2</u> | NO | | | | | |
| <u>3-179694-3</u> | NO | | | | | |
| <u>3-179694-4</u> | NO | | | | | |
| <u>3-179694-5</u> | NO | | | | | |
| <u>3-292215-0</u> | NO | | | | | |
| <u>3-292215-1</u> | NO | | | | | |
| <u>3-292215-2</u> | NO | | | | | |
| <u>3-292215-3</u> | NO | | | | | |
| <u>3-292215-4</u> | NO | | | | | |
| <u>3-292215-5</u> | NO | | | | | |
| <u>3-292215-6</u> | NO | | | | | |
| <u>3-292215-7</u> | NO | | | | | |
| <u>3-292215-8</u> | NO | | | | | |
| <u>3-292215-9</u> | NO | | | | | |
| <u>3-292216-0</u> | NO | | | | | |
| <u>3-292216-2</u> | NO | | | | | |
| <u>3-292216-4</u> | NO | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------|---------------------------|------------------|----------------------|------------------------|---------------------------------|---------------------------|
| <u>3-292216-6</u> | NO | | | | | |
| <u>3-292216-8</u> | NO | | | | | |
| <u>3-353293-0</u> | NO | | | | | |
| <u>3-353293-1</u> | NO | | | | | |
| <u>3-353293-2</u> | NO | | | | | |
| <u>3-353293-3</u> | NO | | | | | |
| <u>3-353293-4</u> | NO | | | | | |
| <u>3-353293-5</u> | NO | | | | | |
| <u>3-353293-6</u> | NO | | | | | |
| <u>3-353293-7</u> | NO | | | | | |
| <u>3-353293-8</u> | NO | | | | | |
| <u>3-353293-9</u> | NO | | | | | |
| <u>353293-2</u> | NO | | | | | |
| <u>353293-3</u> | NO | | | | | |
| <u>353293-4</u> | NO | | | | | |
| <u>353293-5</u> | NO | | | | | |
| <u>353293-6</u> | NO | | | | | |
| <u>353293-7</u> | NO | | | | | |
| <u>353293-8</u> | NO | | | | | |
| <u>353293-9</u> | NO | | | | | |
| <u>4-171825-4</u> | NO | | | | | |
| <u>4-171826-2</u> | NO | | | | | |
| <u>4-173977-2</u> | NO | | | | | |
| <u>4-173977-3</u> | NO | | | | | |
| <u>4-173977-4</u> | NO | | | | | |
| <u>4-173977-5</u> | NO | | | | | |
| <u>4-173977-6</u> | NO | | | | | |
| <u>4-173977-7</u> | NO | | | | | |
| <u>4-173977-8</u> | NO | | | | | |
| <u>4-173977-9</u> | NO | | | | | |
| <u>4-292161-2</u> | NO | | | | | |
| <u>4-292161-4</u> | NO | | | | | |
| <u>4-292215-0</u> | NO | | | | | |
| <u>4-292216-0</u> | NO | | | | | |
| <u>4-292253-2</u> | NO | | | | | |
| <u>4-292253-4</u> | NO | | | | | |
| <u>4-292253-6</u> | NO | | | | | |
| <u>4-353293-0</u> | NO | | | | | |
| <u>5-292215-6</u> | NO | | | | | |
| <u>5-353293-3</u> | NO | | | | | |
| <u>5-353293-6</u> | NO | | | | | |
| <u>6-173977-2</u> | NO | | | | | |
| <u>6-173977-3</u> | NO | | | | | |
| <u>6-173977-4</u> | NO | | | | | |
| <u>6-173977-5</u> | NO | | | | | |
| <u>6-173977-6</u> | NO | | | | | |
| <u>6-173977-7</u> | NO | | | | | |
| <u>6-173977-8</u> | NO | | | | | |
| <u>6-173977-9</u> | NO | | | | | |
| <u>6-292161-2</u> | NO | | | | | |
| <u>6-292161-3</u> | NO | | | | | |
| <u>6-292161-4</u> | NO | | | | | |
| <u>6-292161-5</u> | NO | | | | | |
| <u>6-292161-6</u> | NO | | | | | |
| <u>6-292253-2</u> | NO | | | | | |
| <u>6-353293-1</u> | NO | | | | | |
| <u>6-353293-2</u> | NO | | | | | |
| <u>6-353293-3</u> | NO | | | | | |
| <u>6-353293-4</u> | NO | | | | | |
| <u>6-353293-5</u> | NO | | | | | |
| <u>6-353293-6</u> | NO | | | | | |
| <u>6-353293-7</u> | NO | | | | | |
| <u>6-353293-8</u> | NO | | | | | |
| <u>6-353293-9</u> | NO | | | | | |
| <u>7-173977-0</u> | NO | | | | | |
| <u>7-173977-1</u> | NO | | | | | |
| <u>7-173977-2</u> | NO | | | | | |
| <u>7-173977-4</u> | NO | | | | | |
| <u>7-173977-5</u> | NO | | | | | |
| <u>7-353293-0</u> | NO | | | | | |
| <u>8-292112-2</u> | NO | | | | | |
| <u>8-292112-3</u> | NO | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------|----------------------------------|-------------------------|-----------------------------|-------------------------------|--|----------------------------------|
| <u>8-292112-4</u> | NO | | | | | |
| <u>8-292112-5</u> | NO | | | | | |
| <u>8-292112-6</u> | NO | | | | | |
| <u>8-292112-7</u> | NO | | | | | |
| <u>8-292112-8</u> | NO | | | | | |
| <u>8-292112-9</u> | NO | | | | | |
| <u>8-292142-9</u> | NO | | | | | |
| <u>8-292144-3</u> | NO | | | | | |
| <u>8-292144-4</u> | NO | | | | | |
| <u>8-292144-5</u> | NO | | | | | |
| <u>8-292144-6</u> | NO | | | | | |
| <u>8-292144-7</u> | NO | | | | | |
| <u>8-292144-8</u> | NO | | | | | |
| <u>8-292144-9</u> | NO | | | | | |
| <u>9-292112-0</u> | NO | | | | | |
| <u>9-292112-1</u> | NO | | | | | |
| <u>9-292112-2</u> | NO | | | | | |
| <u>9-292112-3</u> | NO | | | | | |
| <u>9-292112-4</u> | NO | | | | | |
| <u>9-292112-5</u> | NO | | | | | |
| <u>9-292144-0</u> | NO | | | | | |
| <u>9-292144-1</u> | NO | | | | | |
| <u>9-292144-2</u> | NO | | | | | |
| <u>9-292144-3</u> | NO | | | | | |
| <u>9-292144-4</u> | NO | | | | | |
| <u>9-292144-5</u> | NO | | | | | |