

DURATOOL



Hand Held Butane Gas Torch


Model: D03361

IMPORTANT SAFETY INFORMATION

- Never point the tool towards yourself or towards others when lighting or during use.
- Do not touch the tip, nozzle or the main tube when hot.
- Gas canisters contains flammable contents under pressure.
- Do not expose to sparks or naked flame.
- Do not puncture or incinerate the gas canister.
- Check the seals are intact and in good condition before attaching a gas canister.
- Store at temperatures below 40°C (104°F)
- Use only in a well ventilated area.
- This appliance is not intended for use by persons (including children) who are not mentally able, physically capable, experienced or do not understand the product. They should be given supervision and instruction in the use of the appliance by a person responsible for their safety.
- Children should be supervised to ensure that they do not play with the appliance.
- There are no user serviceable parts inside, do not disassemble the unit.
- Ensure the flame is fully extinguished and the tool allowed to cool after use before putting into storage.


CONNECTING A GAS CANNISTER

- Turn the gas control fully clockwise 'OFF' before attaching a gas canister.
- Use only EN417 compliant gas canisters
- Align the tab on the torch collar with the notch in the cannister flange and the torch centrally on the cannister then press the torch down firmly, then turn it clockwise 35° to lock.
- Check that a gas tight connection is made before attempting to light the flame.



OPERATION

- Turn the gas control anti-clockwise to start the gas flowing.
- Press the ignition button to light the flame then release.
- Adjust the flame size using the gas control turning it anti clockwise to increase and clockwise to reduce.
- To turn the torch off, turn the gas control fully clockwise 'OFF'.
- During the initial warm up do not tilt the torch more than approximately 15° from the vertical to avoid flaring. After warming through, the torch can be used at any angle.
- After use allow the torch to fully cool before removing from the gas cannister or putting into storage.



SPECIFICATION

Weight	150g
Fuel	Butane
Dimensions (H x W x D)	42 x 138 x 200mm
Flame temperature	Up to 1300°C



Made in China
PR2 9PP
PO Box 13362 Dublin 2
Man Rev 1.1