



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631
www.littelfuse.com

16th March 2022

Attn: All customers

Subject: Update on PSE Mark certification on certain TR/TE fuses of ratings 1A up to 5A

Dear Valued Customer,

This letter is to communicate that Littelfuse has received the DENAN Statement of Conformity Assessment (PSE Mark - Certification) required for the Japanese Market for the below fuses and ratings.

Affected TR/TE fuses and ratings are as follows:

- 382 series – 1A, 1.25A, 1.6A, 2A, 2.5A, 3.15A, 4A & 5A
- 383 series – 1A, 1.25A, 1.6A, 2A, 2.5A, 3.15A, 4A & 5A
- 400 series – 1A, 1.25A, 1.6A, 2A, 2.5A, 3.15A, 4A & 5A

Please see below list of the affected part numbers;

382 Series	400 Series	383 Series
38211000000	40011000000	38311000000
38211000410	40011000075	38311000410
38211000430	40011000810	38311250000
38211250000	40011000440	38311250410
38211250410	40011250000	38311600000
38211250430	40011250075	38311600410
38211600000	40011250810	38312000000
38211600410	40011250440	38312000410
38211600430	40011600000	38312500000
38212000000	40011600075	38312500410
38212000410	40011600810	38313150000
38212000430	40011600440	38313150410
38212500000	40012000000	38314000000
38212500410	40012000075	38314000410
38212500430	40012000810	38315000000
38213150000	40012000440	38315000410
38213150410	40012500000	
38213150430	40012500075	
38214000000	40012500810	
38214000410	40012500440	



8755 W. Higgins Road
 Suite 500
 Chicago, IL 60631
www.littelfuse.com

38214000430	40013150000	
38215000000	40013150075	
38215000410	40013150810	
38215000430	40013150440	
	40014000000	
	40014000075	
	40014000810	
	40014000440	
	40015000000	
	40015000075	
	40015000810	
	40015000440	

The certificate number for the PSE Mark is NBK040322-JP1021. This certificate will replace the JET1896-31007-2001 for the above 382/383/400 ratings which expired on 2021-09-03.

For reference, below is a table of the “before and after” pictures of the markings on the fuse itself and the labels at the end of this letter for the 382 series 2A as examples.



Littelfuse will start shipping the affected fuses once the fuses are available.

	Before	After
Fuse Marking		



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631
www.littelfuse.com

Label	Before	After
	 <p>38212000000 QTY: 1000 FUSE 250V IEC TL TR6 LL AMMO 2A CAT NO: 38212000 Time-Lag PS E JET A050801 RoHS CE EAC IEC 60127 1&3 SHT4 MADE IN PHILIPPINES</p>	 <p>38212000000 QTY: 1000 FUSE 250V IEC TL TR6 LL AMMO 2A CAT NO: 38212000 Time-Lag PS E A050801 RoHS CE EAC IEC 60127 1&3 SHT4 DATE MADE IN PHILIPPINES</p>

Best regards,
Daniel Wang
Director OverCurrent Products
Electronic Business Unit
Littelfuse, Inc.