



# Product Change Notification

Current Date: 06-Apr-2022

## TE Connectivity

**Product Change Notification:** P-22-022461

**PCN Date:** 05-APR-22

**Customer:** TTI Inc(0000139702)

**Location:** WORLDWIDE

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Self Adhesive Labels for marking wire and Cables

**Description of Changes**

Manufacturing location change. The following Part Numbers will be transferred from the TE plant located at Idento Roedermark Germany to a TE manufacturing plant located in Tangier, Morocco.

**Reason for Changes:**

Dear Customer, as a result of our continuous strive to improve our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according to the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance of the product.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	01-AUG-2022
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1768019-8</a>	NO			"C60516-000", "EET-5176P-8A"			
<a href="#">1-1878914-7</a>	NO						
<a href="#">187752-000</a>	NO			"4-1198202-9", "CR-107-LSR"			
<a href="#">1878865-2</a>	NO						
<a href="#">260206-000</a>	NO			"9-1198197-3", "CR-108-LSR"			
<a href="#">394378-000</a>	NO			"1-1198187-9", "CR-110-LSR"			
<a href="#">4-1768422-3</a>	NO						
<a href="#">416514-000</a>	NO			"307-LE", "7-1198184-3"			
<a href="#">456834-000</a>	NO			"301-LE", "6-1198180-6"			
<a href="#">483818-000</a>	NO			"5-1200012-4", "HPK02WE1050"			
<a href="#">572792-000</a>	NO			"319-LM", "1-1198172-5"			
<a href="#">6-1768018-3</a>	NO			"F49446-000", "EET-1938P-9"			
<a href="#">6-1768019-8</a>	NO			"C62650-000", "EK1119"			
<a href="#">6-1768021-6</a>	NO			"E54351-000", "LBG-F-00010/2"			
<a href="#">6-1768703-0</a>	NO						
<a href="#">7-1768021-2</a>	NO			"C86386-000", "LBG-F-00029"			
<a href="#">7-1768829-1</a>	NO						
<a href="#">8-1768016-3</a>	NO			"E26941-000", "CSL-02713P-9"			
<a href="#">8-1768016-5</a>	NO			"A53263-000", "CSL-03418P-9"			
<a href="#">8-1768016-9</a>	NO			"E69476-000", "CSL-05525P-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">8-1768025-0</a>	NO			"F84313-000", "LBG-U-01484/1"			
<a href="#">9-1768409-8</a>	NO						
<a href="#">9-1768703-6</a>	NO						
<a href="#">958144-000</a>	NO			"325-LM", "1-1198143-9"			
<a href="#">A18923-000</a>	NO			"1201774-1", "HMM-572241-5-8A"			
<a href="#">A37049-000</a>	NO			"8-1200611-9", "HM-762508-2.5-8A"			
<a href="#">A46153-000</a>	NO			"4-1201552-0", "HMM-762381-2.5-8A"			
<a href="#">A83643-000</a>	NO			"8-1200610-6", "HM-762127-1-8A"			
<a href="#">C01371-000</a>	NO			"3-1200609-3", "HW-762127-1-9"			
<a href="#">C21303-000</a>	NO			"1-1200609-3", "HM-508254-5-8A"			
<a href="#">C37234-000</a>	NO			"9-1200609-2", "HM-381191-5-8A"			
<a href="#">C53715-000</a>	NO			"1-1200610-8", "HM-101508-2.5-8A"			
<a href="#">C58122-000</a>	NO			"9-1200607-1", "HW-762508-2.5-9"			
<a href="#">C78178-000</a>	NO			"5-1200608-9", "EP-101165-0.85-9"			
<a href="#">C78183-000</a>	NO			"7-1200607-7", "HM-508318-2.5-8A"			
<a href="#">CC0109-000</a>	NO			"HLX125YW4NEL60S", "3-1899112-6"			
<a href="#">CC0110-000</a>	NO			"HLX125YW2NEL60S", "3-1899112-7"			
<a href="#">CT87273001</a>	NO			"4-1899688-9"			
<a href="#">D07339-000</a>	NO			"6-1200608-7", "HW-191064-10-9"			
<a href="#">D11430-000</a>	NO			"7-1200608-9", "HW-095095-10-9"			
<a href="#">D14091-000</a>	NO			"9-1200608-1", "EP-381191-5-9"			
<a href="#">D34022-000</a>	NO			"5-1200606-9", "EP-254127-10-9"			
<a href="#">D34032-000</a>	NO			"6-1200606-1", "HM-254127-10-8A"			
<a href="#">D57340-000</a>	NO			"5-1200607-5", "EP-508254-5-9"			
<a href="#">D64030-000</a>	NO			"7-1200607-1", "EP-762508-2.5-9"			
<a href="#">D69815-000</a>	NO			"9-1202019-5", "EP-101381-2.5-9"			
<a href="#">D71430-000</a>	NO			"308-LM", "5-1200605-6"			
<a href="#">D88272-000</a>	NO			"5-1200605-7", "HW-381064-10-9"			
<a href="#">D91406-000</a>	NO			"6-1200605-0", "EP-699254-5-9"			
<a href="#">E04109-000</a>	NO			"1-1200606-9", "EP-508508-3-9"			
<a href="#">E14158-000</a>	NO			"9-1200603-8", "HW-127127-10-9"			
<a href="#">E15075-000</a>	NO			"6-1201552-8", "HMM-101635-2.5-8A"			
<a href="#">E21596-000</a>	NO			"4-1200604-1", "EP-101508-2.5-9"			
<a href="#">E24103-000</a>	NO			"4-1200604-2", "HM-699254-5-8A"			
<a href="#">E31556-000</a>	NO			"1-1200604-0", "EP-381127-5-9"			
<a href="#">E61543-000</a>	NO			"1200605-5", "EP-508127-5-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">E64127-000</a>	NO			"1-1200605-1", "HM-101165-0.85-8A"			
<a href="#">E78364-000</a>	NO			"7-1200602-2", "EP-101762-1.8-9"			
<a href="#">E87437-000</a>	NO			"9-1200602-8", "HW-508095-5-9"			
<a href="#">E97411-000</a>	NO			"4-1200603-9", "HW-699254-5-9"			
<a href="#">F05902-000</a>	NO			"EP-762254-5-9", "6-1200835-7"			
<a href="#">F17521-000</a>	NO			"5-1200601-6", "HW-254127-10-9"			
<a href="#">F37539-000</a>	NO			"8-1200601-6", "HM-699191-5-8A"			
<a href="#">F39639-000</a>	NO			"1-1201922-4", "HW-762254-5-9"			
<a href="#">F41698-000</a>	NO			"1-1200602-0", "HW-508127-5-9"			
<a href="#">F61662-000</a>	NO			"5-1200602-3", "HW-318097-10-9"			
<a href="#">F78410-000</a>	NO			"1-1200601-2", "HW-101508-2.5-9"			

Customer: TTI, Inc. ( 1305175 )

Location: Maisach-gerlninden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1768019-8</a>	NO		TYC1-1768019-8	"C60516-000", "EET-5176P-8A"			
<a href="#">187752-000</a>	NO		TYC187752-000, RAY187752-000	"4-1198202-9", "CR-107-LSR"			
<a href="#">260206-000</a>	NO		TYC260206-000, RAY260206-000	"9-1198197-3", "CR-108-LSR"			
<a href="#">4-1768422-3</a>	NO		TYC4-1768422-3				
<a href="#">6-1768018-3</a>	NO		TYC6-1768018-3	"F49446-000", "EET-1938P-9"			
<a href="#">6-1768019-8</a>	NO		TYC6-1768019-8	"C62650-000", "EK1119"			
<a href="#">6-1768021-6</a>	NO			"E54351-000", "LBG-F-00010/2"			
<a href="#">6-1768703-0</a>	NO		TYC6-1768703-0				
<a href="#">7-1768021-2</a>	NO		TYC7-1768021-2	"C86386-000", "LBG-F-00029"			
<a href="#">7-1768829-1</a>	NO		TYC7-1768829-1				
<a href="#">8-1768016-3</a>	NO		TYC8-1768016-3	"E26941-000", "CSL-02713P-9"			
<a href="#">8-1768016-5</a>	NO		TYC8-1768016-5	"A53263-000", "CSL-03418P-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<del>8-1768016-9</del>	NO		TYC8-1768016-9	"E69476-000", "CSL-05525P-9"			
<del>8-1768025-0</del>	NO		TYC8-1768025-0	"F84313-000", "LBG-U-01484/1"			
<del>9-1768409-8</del>	NO		TYC9-1768409-8				
<del>9-1768703-6</del>	NO		TYC9-1768703-6				
<del>C78178-000</del>	NO			"5-1200608-9", "EP-101165-0.85-9"			
<del>CC0109-000</del>	NO		RAYCC0109-000	"HLX125YW4NEL60S", "3-1899112-6"			
<del>CC0110-000</del>	NO		RAYCC0110-000	"HLX125YW2NEL60S", "3-1899112-7"			
<del>F05902-000</del>	NO		TYCF05902-000	"EP-762254-5-9", "6-1200835-7"			
<del>F61662-000</del>	NO		RAYF61662-000	"5-1200602-3", "HW-318097-10-9"			

Customer: TTI, Inc. ( 3057778 )

Location: Maisach-gerlninden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<del>187752-000</del>	NO		TYC187752-000, RAY187752-000	"4-1198202-9", "CR-107-LSR"			
<del>260206-000</del>	NO		TYC260206-000, RAY260206-000	"9-1198197-3", "CR-108-LSR"			
<del>4-1768422-3</del>	NO		TYC4-1768422-3				
<del>6-1768018-3</del>	NO		TYC6-1768018-3	"F49446-000", "EET-1938P-9"			
<del>6-1768019-8</del>	NO		TYC6-1768019-8	"C62650-000", "EK1119"			
<del>6-1768021-6</del>	NO			"E54351-000", "LBG-F-00010/2"			
<del>6-1768703-0</del>	NO		TYC6-1768703-0				
<del>7-1768021-2</del>	NO		TYC7-1768021-2	"C86386-000", "LBG-F-00029"			
<del>7-1768829-1</del>	NO		TYC7-1768829-1				
<del>8-1768016-3</del>	NO		TYC8-1768016-3	"E26941-000", "CSL-02713P-9"			
<del>8-1768016-5</del>	NO		TYC8-1768016-5	"A53263-000", "CSL-03418P-9"			
<del>8-1768016-9</del>	NO		TYC8-1768016-9	"E69476-000", "CSL-05525P-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">8-1768025-0</a>	NO		TYC8-1768025-0	"F84313-000", "LBG-U-01484/1"			
<a href="#">9-1768409-8</a>	NO		TYC9-1768409-8				
<a href="#">9-1768703-6</a>	NO		TYC9-1768703-6				
<a href="#">C78178-000</a>	NO			"5-1200608-9", "EP-101165-0.85-9"			
<a href="#">CC0109-000</a>	NO		RAYCC0109-000	"HLX125YW4NEL60S", "3-1899112-6"			
<a href="#">CC0110-000</a>	NO		RAYCC0110-000	"HLX125YW2NEL60S", "3-1899112-7"			
<a href="#">F05902-000</a>	NO		TYCF05902-000	"EP-762254-5-9", "6-1200835-7"			
<a href="#">F61662-000</a>	NO		RAYF61662-000	"5-1200602-3", "HW-318097-10-9"			

Customer: TTI Inc ( 168830 )

Location: Fort Worth

Agreement Number: TTI003

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1878914-7</a>	NO						
<a href="#">1878865-2</a>	NO						
<a href="#">483818-000</a>	NO			"5-1200012-4", "HPK02WE1050"			
<a href="#">572792-000</a>	NO			"319-LM", "1-1198172-5"			
<a href="#">C37234-000</a>	NO			"9-1200609-2", "HM-381191-5-8A"			
<a href="#">D69815-000</a>	NO			"9-1202019-5", "EP-101381-2.5-9"			
<a href="#">D91406-000</a>	NO			"6-1200605-0", "EP-699254-5-9"			
<a href="#">E04109-000</a>	NO			"1-1200606-9", "EP-508508-3-9"			
<a href="#">F05902-000</a>	NO			"EP-762254-5-9", "6-1200835-7"			
<a href="#">F41698-000</a>	NO			"1-1200602-0", "HW-508127-5-9"			

Customer: TTI Inc ( 1281288 )

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">394378-000</a>	NO			"1-1198187-9", "CR-110-LSR"			
<a href="#">416514-000</a>	NO			"307-LE", "7-1198184-3"			
<a href="#">456834-000</a>	NO			"301-LE", "6-1198180-6"			
<a href="#">572792-000</a>	NO			"319-LM", "1-1198172-5"			
<a href="#">958144-000</a>	NO			"325-LM", "1-1198143-9"			
<a href="#">A18923-000</a>	NO			"1201774-1", "HMM-572241-5-8A"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">A37049-000</a>	NO			"8-1200611-9", "HM-762508-2.5-8A"			
<a href="#">A46153-000</a>	NO			"4-1201552-0", "HMM-762381-2.5-8A"			
<a href="#">A83643-000</a>	NO			"8-1200610-6", "HM-762127-1-8A"			
<a href="#">C01371-000</a>	NO			"3-1200609-3", "HW-762127-1-9"			
<a href="#">C21303-000</a>	NO			"1-1200609-3", "HM-508254-5-8A"			
<a href="#">C37234-000</a>	NO			"9-1200609-2", "HM-381191-5-8A"			
<a href="#">C53715-000</a>	NO			"1-1200610-8", "HM-101508-2.5-8A"			
<a href="#">C58122-000</a>	NO			"9-1200607-1", "HW-762508-2.5-9"			
<a href="#">C78178-000</a>	NO			"5-1200608-9", "EP-101165-0.85-9"			
<a href="#">C78183-000</a>	NO			"7-1200607-7", "HM-508318-2.5-8A"			
<a href="#">CT87273001</a>	NO			"4-1899688-9"			
<a href="#">D07339-000</a>	NO			"6-1200608-7", "HW-191064-10-9"			
<a href="#">D11430-000</a>	NO			"7-1200608-9", "HW-095095-10-9"			
<a href="#">D14091-000</a>	NO			"9-1200608-1", "EP-381191-5-9"			
<a href="#">D34022-000</a>	NO			"5-1200606-9", "EP-254127-10-9"			
<a href="#">D34032-000</a>	NO			"6-1200606-1", "HM-254127-10-8A"			
<a href="#">D57340-000</a>	NO			"5-1200607-5", "EP-508254-5-9"			
<a href="#">D64030-000</a>	NO			"7-1200607-1", "EP-762508-2.5-9"			
<a href="#">D69815-000</a>	NO			"9-1202019-5", "EP-101381-2.5-9"			
<a href="#">D71430-000</a>	NO			"308-LM", "5-1200605-6"			
<a href="#">D88272-000</a>	NO			"5-1200605-7", "HW-381064-10-9"			
<a href="#">D91406-000</a>	NO			"6-1200605-0", "EP-699254-5-9"			
<a href="#">E14158-000</a>	NO			"9-1200603-8", "HW-127127-10-9"			
<a href="#">E15075-000</a>	NO			"6-1201552-8", "HMM-101635-2.5-8A"			
<a href="#">E21596-000</a>	NO			"4-1200604-1", "EP-101508-2.5-9"			
<a href="#">E24103-000</a>	NO			"4-1200604-2", "HM-699254-5-8A"			
<a href="#">E31556-000</a>	NO			"1-1200604-0", "EP-381127-5-9"			
<a href="#">E61543-000</a>	NO			"1200605-5", "EP-508127-5-9"			
<a href="#">E64127-000</a>	NO			"1-1200605-1", "HM-101165-0.85-8A"			
<a href="#">E78364-000</a>	NO			"7-1200602-2", "EP-101762-1.8-9"			
<a href="#">E87437-000</a>	NO			"9-1200602-8", "HW-508095-5-9"			
<a href="#">E97411-000</a>	NO			"4-1200603-9", "HW-699254-5-9"			
<a href="#">F05902-000</a>	NO			"EP-762254-5-9", "6-1200835-7"			
<a href="#">F17521-000</a>	NO			"5-1200601-6", "HW-254127-10-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">F37539-000</a>	NO			"8-1200601-6", "HM-699191-5-8A"			
<a href="#">F39639-000</a>	NO			"1-1201922-4", "HW-762254-5-9"			
<a href="#">F61662-000</a>	NO			"5-1200602-3", "HW-318097-10-9"			
<a href="#">F78410-000</a>	NO			"1-1200601-2", "HW-101508-2.5-9"			