



infrastructure for a connected world

## PRODUCT CHANGE NOTIFICATION

Product Category LABELING SYSTEMS **20220615-1**

Product Group ID AND SAFETY

ISSUE DATE:  NA  MEA  15-Jun-22

DISCONTINUATION  LATAM

IMPACTED REGIONS:  OTHER

REASON FOR CHANGE:

### DESCRIPTION OF CHANGE: (Required)

Part numbers LS8E, LS8EQ, LS8E-KIT, LS8EQ-KIT, LS8E-KIT-ACS, LS8EQ-KIT-ACS, LS8E-KIT-ACE, and LS8EQ-KIT-ACE will be discontinued. The replacement for the LS8E and LS8EQ printers is part number MP300 for North America, and part number MP300/E for international use. The label cassettes and accessories for the LS8E and LS8EQ will not be discontinued.

Photos/Drawing (where applicable)

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	6	15
Old product discontinuation date*	2022	12	31

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

**CUSTOMER SERVICE CONTACTS**

<b>ASIA PACIFIC</b>	<b>AUSTRALIA: 1-800 7263848</b> <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	<b>CHINA: 400-820-1900</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>HONG KONG: 800-965768</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	<b>INDIA: 000 800 6501844 (Fixed)</b> 000 800 6500369 (Mobile) <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>INDONESIA: 001 803 65 7571</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>JAPAN: +81-3-6863-6000</b> <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	<b>TAIWAN: 0080 165 1487</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
	<b>LATIN AMERICA</b>	<b>BRAZIL 08000562613 (Toll Free)</b> <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520</b> 01 800 360 86 00 (Toll Free) <a href="mailto:MEX-customer-service@panduit.com">MEX-customer-service@panduit.com</a>	<b>OTHER LA COUNTRIES:</b> Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	<b>EMEA: +44 208 6017219</b> <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

To add a contact or to unsubscribe, please send an email to:

[PCN@panduit.com](mailto:PCN@panduit.com)

<b>IMPACTED PART NUMBER(s)</b>	<b>Replacement Part</b>
LS8E	MP300
LS8EQ	MP300
LS8E-KIT	MP300
LS8EQ-KIT	MP300
LS8E-KIT-ACS	MP300
LS8EQ-KIT-ACS	MP300
LS8E-KIT-ACE	MP300/E
LS8EQ-KIT-ACE	MP300/E