



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M001078I

DATE: 15-Jul-2022

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------|-------------------|-------------------------|-----------------|--------------------|------------------------------------|
| Discontinuance | MAX944EPD+ | N/A | 15-Jul-2022 | 15-Jul-2022 | Part can no longer be manufactured |
| Discontinuance | MAXM17930AME+ | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17930AME+T | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17931AME+ | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17931AME+T | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17932AME+ | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17932AME+T | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17937AME+ | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17937AME+T | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17938AME+ | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17938AME+T | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17939AME+ | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |
| Discontinuance | MAXM17939AME+T | N/A | 15-Jul-2022 | 15-Jul-2022 | The part was not released |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Aug-2022