



01-Sep-2022

**PCN #:** PCN-22-150784

**Subject :** RF connectors

**Description of Change :** 1) Manufacturing location change. Following part numbers will be transferred from America to China. 2) Following part numbers will be reactivated. 3) The default color of gasket/O-Ring will be red except specified in customer drawing. 4) Optimize design and process.5) Optimize packaging type based on current plant.

**Reason :** Parts will be reactivated and manufactured under an alternate plant based in China.

**Key Dates :**

<b>Product Affected</b>	<b>Alias Part Number</b>	<b>Substitute Part Number</b>	<b>AliasSub Part Number</b>
1052552-1	"2052-1352-02"		
51421-2			
5051426-4			
51426-2			
1053265-1	"2058-5329-02"		
1408314-1	"010-5994-00"		
1050525-1	"2001-5003-02"		
1052902-1	"2052-5674-02"		
1052689-1			
1052566-1			
1408313-1			
5051426-2			
1054869-1			
5051426-5			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.