



Product Change Notification

| | | | |
|---|---|---------------------|--------|
| Date Issued : | September 20, 2022 | PCN Number : | 512693 |
| Reason for Change : | Obsolete | | |
| Description of Change : | <p>We are issuing a modified PCN for OBS PCN#512249 to update you on additional information when ordering impacted parts 54548**33/**71, 54550**33/**71.</p> <p>As we communicated to you recently, as of August 17th, Molex is no longer able to ship the impacted materials with a UL certification label to you. We have been instructed by UL to remove the label on these parts shipping after this date. We provided you the option of accepting delivery upon agreeing to a waiver relating to flammability and the lack of UL certifications of the Affected Toray Resins.</p> <p>At the time of this letter, we have not received a signed waiver from your company. As a result, your current open orders have been placed on shipment hold until a signed waiver is received. After, September 30, 2022, orders in our system without a customer signed waiver will be cancelled.</p> <p>If you would like to order a replacement part, or cancel existing orders for impacted parts please contact your Molex Account Representative.</p> | | |
| Reason for Short Notice : | Update Previously Issued Change Notice | | |
| Planned Implementation Date : | September 30, 2022 | | |
| Recommended replacement parts : | Please see the attached replacement parts list .xls file. | | |
| Last Time Buy Date for Obsolete Parts : | September 30, 2022 | | |
| Last Time Ship Date for Obsolete Parts : | September 30, 2022 | | |

Before Picture

Overview

- **Product Impact**
 - **Obsolescence with Replacement**
 - See attached for Impacted part list vs Replacement Part List
 - Replacement Part is No impact to Form, Fit or Function.
 - LTB/LTS dates are immediate

| Contents | Impacted | Replacement |
|-------------|--|--|
| Part Number | 54548**33, 54548**71 54550**33, 54550**71 | 54548**34, 54548**72 54550**34, 54550**72 |
| Resin | TORAY LCP UL-94 V0 (Revocation) | SUMITOMO LCP UL-94 V0 |

"After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned.

For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquiries regarding this PCN by clicking on the below link

mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512693

or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512693** " in the e-mail Subject line for faster response.

[Molex, LLC](#)

2222 Wellington Court

Lisle, IL 60532

TEL (800) 786-6539

www.molex.com