



infrastructure for a connected world

## PRODUCT CHANGE NOTIFICATION

Product Category SAFETY PRODUCTS **20220902-1**

Product Group ID AND SAFETY

ISSUE DATE:  NA  MEA  LATAM  AP-Sep-22

IMPACTED REGIONS:  DISCONTINUATION

REASON FOR CHANGE:  OTHER

### DESCRIPTION OF CHANGE: (Required)

Listing of select safety product part numbers that are being discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	9	2
Old product discontinuation date*	2022	11	30

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

**CUSTOMER SERVICE CONTACTS**

<b>ASIA PACIFIC</b>	<b>AUSTRALIA: 1-800 7263848</b> <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	<b>CHINA: 400-820-1900</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>HONG KONG: 800-965768</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	<b>INDIA: 000 800 6501844 (Fixed)</b> 000 800 6500369 (Mobile)  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>INDONESIA: 001 803 65 7571</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>JAPAN: +81-3-6863-6000</b>  <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	<b>TAIWAN: 0080 165 1487</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
	<b>LATIN AMERICA</b>	<b>BRAZIL 08000562613 (Toll Free)</b>  <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520</b> 01 800 360 86 00 (Toll Free)  <a href="mailto:MEX-customerservice@panduit.com">MEX-customerservice@panduit.com</a>	<b>OTHER LA COUNTRIES:</b> Phone USA 1-708-532-1800  <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300  <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>  <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>		

To add a contact or to unsubscribe, please send an email to:

[PCN@panduit.com](mailto:PCN@panduit.com)

<b>IMPACTED PART NUMBER(s)</b>	<b>Replacement Part</b>
PBB0024	NO-REPLACEMENT
PBB0041	NO-REPLACEMENT
PLVS0507D7156	NO-REPLACEMENT
PSL-PC38-33	PSL-MLDC
PSL-SC	NO-REPLACEMENT
PSL-TG1	NO-REPLACEMENT
PVT-1016-Q	NO-REPLACEMENT
PVT-1017-Q	PVT-41
PVT-1125	PVT-161-Q
WL1	NO-REPLACEMENT