

PRODUCT CHANGE NOTIFICATION

Product Category OUTLETS 20221021-1

Product Group ROAR

ISSUE DATE: ☒ NA ☒ EMEA ☒ LATAM ☒ AP1-Oct-22

☐ DISCONTINUATION

REASON FOR CHANGE: ☒ OTHER

DESCRIPTION OF CHANGE: (Required)

Changes to the metal wrap found on the SmartKeeper USBA blockout device (SKUSBA-V) will result in a slightly different look compared to the existing offering. This will not affect the performance and will not be visible after installation. This will be a running change so part number will remain the same.

Photos/Drawing (where applicable)



Current

New

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	11	4
Old product discontinuation date*			

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

IMPACTED PART NUMBER
SKUSBA-V