


Before Picture

Overview

 For 78171 series & 205871 series embosses tape design change which to ensure continuous improvement and prevent damage housing issue recurrence. After Picture

Overview

This notification is to inform about part(s) listed will undergo changes to the design for series 78171000X
205871000X embossed tape. No changes will be made to the product as a result of this change.



- Molex Malaysia Part Number(s) Affected: Refer to part number listed
- Product Impact
 - This change is to ensure continuous improvement and prevent damage housing issue recurrence. The material is produced per Molex specification. There is no change in product design and process for Molex Malaysia, therefore no change in the Molex assembly part number will occur either.
- Qualification/Drop test available upon request.



Additional Information:



3

RELEASED

You may address inquires regarding this PCN by clicking on the below link mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512774 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 512774" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com