



MICRON_eMMC v5.1 153b and 100b (Automotive) Assembly Site Transition from MMY, Malaysia to MSB, Singapore

PCN: 34883

Published: 2022-12-12

Type:	Manufacturing Site - Change or Addition
Description:	<p>To align with Automotive strategy, Micron is initiating an assembly site transition from MMY, Malaysia to MSB - Singapore for the below listed products. MSB is Micron's Center of Excellence for automotive assembly quality.</p> <p>Samples from MSB are expected to be available the end of July 2023. Please work with your Micron representative on transition plans which are expected to begin with samples July 28, 2023. Please ensure all orders for product from MMY are placed by December 29, 2023 as shipments from MMY will end by June 28, 2024.</p> <p>Current:</p> <p>MMY - Micron Semiconductor Malaysia - No K93 (PLO74) Jalan Perindustrian 7 Kawasan Perindustrian Taniung Agas, Muar, JO, Malaysia 84007</p> <p>Future:</p> <p>MMY - Micron Semiconductor Malaysia - No K93 (PLO74) Jalan Perindustrian 7 Kawasan Perindustrian Taniung Agas, Muar, JO, Malaysia 84007</p> <p>MSB - Micron Semi Asia Operations - 990 Bendemeer Road, Singapore 339942, Singapore</p>
Reason:	Manufacturing Efficiency
Product Affected:	J35A(8GB): 100b and 153b, AIT and AAT parts J56X(32GB) both 100b and 153b, AIT and AAT parts

Affected Micron Part Number <u>COMPONENT</u>	Recommended Replacement	Customer Part Number
MTFC16GAPALBH-AAT		MICMTFC16GAPALBH!B, MICMTFC16GAPALB>>>
MTFC16GAPALBH-AIT		MICMTFC16GAPALBH->, MICMTFC16GAPALBH!A
MTFC16GAPALGT-AAT		A2C0452740000, MICMTFC16GAPALGT->
MTFC16GAPALNA-AAT		MICMTFC16GAPALNA>>
MTFC16GAPALNA-AIT		A2C0407540000, A2C0393190000, MICMTFC16GAPALNA->, MTFC16GAPALNA-AIT TR
MTFC64GAPALNA-AIT		
MTFC8GAMALBH-AAT		A2C0331080000, A2C0312650000, A2C0355980000, A2C0401990000, A2C0445500000, AAA2127220000, AAA2187570000, A2C0383930000, AAA2273780000, AAA2190240000, MICMTFC8GAMALBHAAT, MICMTFC8GAMALBHA!B, MICMTFC8GAMALBH-A>, MTFC8GAMALBH-AAT TR
MTFC8GAMALBH-AIT		MICMTFC8GAMALBH->>
MTFC8GAMALHT-AAT		
MTFC8GAMALNA-AAT		8909009743, MICMTFC8GAMALNA-A>, MICMTFC8GAMALNAAAT
MTFC8GAMALNA-AIT		MICMTFC8GAMALNAAIT, MICMTFC8GAMALNA->>

*Materials that have been ordered are in **bold**.

Method of Identification: Please refer to Micron's Customer Service Note - Product Marks, Product Labels, and Packaging Labels CSN-11 for details on Product Marks and Labels specific to the codes for countries of encapsulation.

Micron Sites Affected: MMY – Micron Semiconductor Malaysia

MSB – Micron Semi Asia Operations

Sample Available:	2023-07-28
Qualification Reports Available:	2023-07-28
Product Ship Date:	2023-10-26

DISCLAIMER: INFORMATION IN THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS WITHOUT WARRANTIES OF ANY KIND. INFORMATION REGARDING PRODUCTS, INCLUDING STATEMENTS REGARDING PRODUCT FEATURES, AVAILABILITY, FUNCTIONALITY, OR COMPATIBILITY, ARE PROVIDED FOR INFORMATIONAL PURPOSES ONLY AND DO NOT MODIFY THE WARRANTY, IF ANY, APPLICABLE TO ANY PRODUCT, AND MICRON DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY RELATING TO SALE AND/OR USE OF PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT.

NOTE: Per JEDEC Standard J-STD-046 Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.