

IloT Product Change Notice


The change will be applied on the ULI-422C (BB-UHR402). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

Note: The ordering process has not been changed. Customers should continue to order model number BB-UHR402.

- Reason for the Change:** Branding
- Affected Products:** ULI-422C (BB-UHR402)
- Impact on Application:** No change to form, fit, or function.

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	No.
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ULI-422C BB-UHR402	20BB250- 10898-00	1990039364T010	Label	 <p>Old Name Plate New Name Plate</p>	Branding

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ULI-422C (BB-UHR402)	ECOM-195130	2/28/2023	Running Change	Name Plate Change

*Note: Cut-in progress depends on factory production schedule.

** Note: The ordering process has not been changed. Customers should continue to order model number BB-UHR402

Contact Windows

PM	Brian Foster / brian.foster@advantech.com
AE	N/A