

Product Advisory

Issue Date: December 21, 2022

Change Type:

Packaging update for NICs to consolidate labeling.

Description and Extent of Change:

The NIC Serial Number and Carton ID labels will be consolidated into the Bulk ID label.

Current Carton Label



New Carton Label



BRCM PN: BCM957504-P425G	
From : FUJU PRECISION COMPONENT COMPANY LIMITED Lot H1 & Lot F, Quang Chau Industrial Park, Van Trung Commune, Viet Yen District, Bac Giang Province, Viet Nam	To : Avago Technologies International Sales@/c/o Avago Technologies (M) Sdn Bhd (RECEIVING), Malaysia, Malaysia
(B) OP ID: P425G18YYYYYY MO: 0987654321	
(P) CUSTOMER PART NUMBER: BCM957504-P425G REV: 18	
(Q) QUANTITY: 10	
(D) DESCRIPTION: P425G Thor 4 x 25G NIC Generic	
Serial Numbers:	
P425G-YYYY-CXXXX-FG	P425G-YYYY-CXXXX-FG
P425G-YYYY-CXXXX-FG	P425G-YYYY-CXXXX-FG
P425G-YYYY-CXXXX-FG	P425G-YYYY-CXXXX-FG
P425G-YYYY-CXXXX-FG	P425G-YYYY-CXXXX-FG
P425G-YYYY-CXXXX-FG	P425G-YYYY-CXXXX-FG
PKG WGT: 0.56 Kg	
1 6 5 0 8 6 1 0 0 6 3 5 7	BCM425-4P

Reasons for Change:

The change is being implement to further enhance supply continuity and standardize package labeling across the product line.



Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

Effective Date of Change:

The part number revision will be incremented to track this update. Product shipments start after February 1, 2023.

Parts Affected:

Part Number	Revision Number	New Revision Number
BCM95719A1904AC	18	19
BCM95719N1905C	13	14
BCM95719N1905CI	2	3
BCM95720A2003AC	15	16
BCM95720A2003ACBLK	14	15
BCM957412A4120AC	17	18
BCM957412M4122C	14	15
BCM957412N4120C	19	20
BCM957412N4120CI	4	5
BCM957414A4140C	12	13
BCM957414A4142CC	20	21
BCM957414M4142C	15	16
BCM957414M4143C	16	17
BCM957414N4140C	20	21
BCM957416A4160C	11	12
BCM957416M4163C	10	11
BCM957416N4160C	15	16
BCM957416N4160CI	3	4
BCM957502-N150FGB	5	6
BCM957502-N150G	13	14
BCM957504-M1100G16	10	11
BCM957504-M1100GB	6	7
BCM957504-M1100GBQ	6	7
BCM957504-N1100FH	3	4
BCM957504-N1100FXB	5	6
BCM957504-N1100FY4	5	6
BCM957504-N1100FY4Q	5	6
BCM957504-N1100FYB	4	5
BCM957504-N1100FYC	4	5
BCM957504-N1100FYCQ	8	9
BCM957504-N1100FZB	5	6
BCM957504-N1100G	29	30
BCM957504-N1100GD	6	7
BCM957504-N1100GI	5	6
BCM957504-N2100GI	2	3
BCM957504-N425G	29	30



BCM957504-P425G	21	22
BCM957508-N1200FX	3	4
BCM957508-N1200FXQ	4	5
BCM957508-N1200FY4	2	3
BCM957508-N1200FZ	2	3
BCM957508-N1200FZQ	3	4
BCM957508-N2100G	28	29
BCM957508-N2100GD	4	5
BCM957508-N2100GDQ	5	6
BCM957508-N2100GI	3	4
BCM957508-P1200G	2	3
BCM957508-P2100G	27	28
BCM957508-P2100GQ	6	7

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.