

Product Change Notice

Issue Date: 27-December-2022

Change Description:

Introduction of new die source

Parts Affected:

ASMT-QBB3-NBD0E	ASMT-QGBE-NGJ0E	ASMT-QWBB-NGHHE	ASMT-QWBB-NHH0E
ASMT-QWBB-NHHQE	ASMT-QWBC-NJK0E	ASMT-QWBC-NJKLE	ASMT-QWBF-NKL0E
ASMT-QWBF-NKLWE	ASMT-QWBG-NFHCE	ASMT-QWBG-NFHDE	ASMT-QYBB-NGH0E
QSMT-QWSN-NGJCE	QSMT-QWGR-NJKGE	QSMT-QWDL-NJKZE	QSMT-QWBF-NKLWE
QSMT-QWB1-NKLFE	AZMT-QWBC-NJKCE	AZMT-QWBF-NKLQE	AZMT-QWBF-NKLRE
AZMT-QWBF-NKLWE	QZMT-QWWA-NJKZE	QZMT-QWSB-NKLRE	QZMT-QWPS-NKLZE
QZMT-QWGR-NJKGE			

Description and Extent of Change:

Introduce new die source for above part numbers


Reasons for Change:

End of life of current die source

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There will be no change on fit, form, function, quality and reliability of final product.

Only Vf characteristics of ASMT-QGBE-NGJ0E is slightly different compared to current die source as illustrated below.





Effective Date of Change:

Parts with above change will commence 30 days after issuance date above.

Qualification Data:

No change in reliability performance. Product and qualification data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.