

Product Discontinuation



PD_093_21

■ Last Order Date: 2022-12-31

■ Last Delivery Date: 2023-09-30

Reason: Product portfolio rationalization

DISCONTINUED				NEW (REPLACEMENT)			
Sales Name	SP Number	OPN	Package	Sales Name	SP Number	OPN	Package
RX98-4	SP000743706	RX984XUMA1	PG-TSSOP-28	TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28
TDA5200	SP000016381	TDA5200XUMA1	PG-TSSOP-28	TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28
TDA5201	SP000012902	TDA5201XUMA1	PG-TSSOP-28	TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28
TDA5210	SP000016384	TDA5210XUMA1	PG-TSSOP-28	TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28
TDA5211	SP000016390	TDA5211XUMA1	PG-TSSOP-28	TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28
TDA5220	SP000014342	TDA5220XUMA1	PG-TSSOP-28	TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28
TDA7200	SP000296473	TDA7200XUMA1	PG-TSSOP-28	TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28
TDA7210	SP000524274	TDA7210XUMA1	PG-TSSOP-28	TDA5240	SP000550860	TDA5240XUMA1	PG-TSSOP-28

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.