•••••

PRODUCT CHANGE NOTIFICATION MAGNETICS

•

•



Bourns® Model SRR6038 and PM638S Series Shielded Power Inductors Addition of Manufacturing Site

Riverside California – January 25, 2023 – To accommodate increasing demand, effective March 5, 2023, Bourns will establish a new additional manufacturing site in China for the Model SRR6038 and PM638S Series Shielded Power Inductors.

A list of affected part numbers is included below.

Affected Part Numbers					
SRR6038-100Y	SRR6038-330Y	SRR6038-6R2Y	PM638S-120-RC	PM638S-3R3-RC	PM638S-820-RC
SRR6038-101Y	SRR6038-390Y	SRR6038-7R4Y	PM638S-150-RC	PM638S-470-RC	PM638S-8R7-RC
SRR6038-120Y	SRR6038-3R3Y	SRR6038-820Y	PM638S-180-RC	PM638S-560-RC	
SRR6038-150Y	SRR6038-470Y	SRR6038-8R2Y	PM638S-220-RC	PM638S-5R0-RC	
SRR6038-180Y	SRR6038-560Y	SRR6038-8R7Y	PM638S-270-RC	PM638S-680-RC	
SRR6038-220Y	SRR6038-5R0Y	PM638S-100-RC	PM638S-330-RC	PM638S-6R2-RC	
SRR6038-270Y	SRR6038-680Y	PM638S-101-RC	PM638S-390-RC	PM638S-7R4-RC	

The new additional manufacturing plant in China uses the same design, material and manufacturing process as the existing plant. The power inductors produced at the additional manufacturing site will meet the same data sheet specifications as the inductors from the existing plant.

The form, fit, function and country of origin of the inductors from the new manufacturing plant will be the same as those from the existing plant. The guality, reliability and production lead time of the inductors from the new manufacturing plant should be the same as those from the existing plant. Traceability will be maintained through lot code and date code.

Samples of inductors made at the new additional manufacturing site are available upon request. Bourns recommends that customers test samples of the affected part numbers from the new manufacturing plant in their specific applications for verification of satisfactory performance.

The implementation date is as follows:

Date that deliveries of products manufactured at both manufacturing sites will begin: March 5, 2023 First date code using the above change: 2310

Orders for the affected part numbers received after March 5, 2023 may be filled interchangeably from the existing manufacturing plant or the new additional manufacturing plant.

If you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC22149