



07-Mar-2023

PCN #: PCN-23-168341

Subject : AMPLIMITE HDP Right Angle

Description of Change : Please be aware of an upcoming Plating change to the listed part numbers.
Before: Board-lock plating is Bright Tin.
After: Board-lock plating is Matte Tin.
Reference performance test data: Matte-tin has same performance

Reason : Change made to the Plating of Board-lock.

Key Dates :

Contact By Date:08-May-2023

Implementation Date:08-May-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
8-338170-2			
2-106507-2			
8-106505-2			
6-338170-2			
1-338169-2			
8-338168-2			
5-338169-2			
5-338170-2			
106505-2			
6-338168-2			
2-106505-2			
3-106506-2			
5-106505-2			
3-338169-2			
3-338170-2			

6-106507-2			
2-106506-2			
8-338169-2			
1-338168-2			
3-106505-2			
2-338170-2			
3-106507-2			
8-106506-2			
1-106506-2			
6-106506-2			
8-106507-2			
338168-2			
2-338169-2			
1-106507-2			
106506-2			
338169-2			
3-338168-2			
1-338170-2			
6-338169-2			
5-106506-2			
1-106505-2			
2-338168-2			
6-106505-2			
106507-2			
338170-2			
5-338168-2			
5-106507-2			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product

Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.