Infonote

AO-IN-2022-017-I

Introduction of new chip and update of datasheet for Radial SFH 313 FA and SFH 314 FA

Published by ams-OSRAM AG Tobelbader Strasse 30, 8141 Premstaetten, Austria Phone +43 3136 500-0 ams-osram.com © All rights reserved



CALL OSRAM

09.03.2023

Dear Customer,

please take note of this Infonote.

This customer notification is for information only and does not require customer approval.

Objective:	Introduction of new chip and update of datasheet for Radial SFH 313 FA and SFH 314 FA	
Affected products:	Radial SFH 313FA and SFH 314FA	
Reason for change:	Datasheet review and adjustment of typically values to reflect production characteristics independent from chip in use.	
Reason for onange.	Current supplier discontinued production; therefore a new chip will be introduced into Radial SFH 313FA and SFH 314FA.	
	Current status	New status
	Datasheet Version 1.4	Datasheet Version 1.5
Description of change:	Supplier A / Austria	Supplier A / Austria Supplier B / Taiwan
	Please refer to customer information package for more details.	
Time schedule:	Updated datasheets are available	
Assessment:	No changes in fit, form, function and reliability.	
Documentation:	Customer information package OS-PCN-2022-017-I	

Published by ams-OSRAM AG Tobelbader Strasse 30, 8141 Premstaetten, Austria Phone +43 3136 500-0 ams-osram.com © All rights reserved