

## IloT Product Change Notice

The change(s) will be applied on the affected products, if you need more information or special support, please contact PM: [Winston.Chen](mailto:Winston.Chen) (TEL: +886-2-7732-3399, ext: **1093**; e-Mail:

[winston.chen@advantech.com.tw](mailto:winston.chen@advantech.com.tw)

**1. Reason for the Change:** [Optimizing Supply status of Product series.](#)

**2. Affected Product:** [TPC-107W-N31YA/TPC-107W-N31AA/TPC-110W-N31YA/TPC-110W-N31AA/TPC-115W-N31YA/TPC-115W-N31A](#)

**3. Impact on Application:**

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	Yes
Impact on Environment Characteristics	No
Impact on Board Certifications	No
Physical Outlook Change	No
Ordering P/N Change	Yes
Cut-in Implement	Work order from Apr. 2023

**4. Description of the Change(s):**

Component Category	Reason of change	Impact on Spec / Software
Core power IC (Power Stage)	Component was phased out by supplier.	No
Load Switch	Component is in short of supply. Add 2nd source for increasing flexibility.	No
LAN Chip Realtek RTL8211FS-CG	Component was in short of Supply (QUALCOMM AR8035-AL1B-R) by supplier.	YES

Model	Part Number Impact		schedule	
	Before	After	Sample	MP
TPC-100W	TPC-107W-N31YA	TPC-107W-N31YB	Mar End	Apr
	TPC-107W-N31AA	TPC-107W-N31AB	Apr End	May
	TPC-110W-N31YA	TPC-110W-N31YB	Mar End	Apr
	TPC-110W-N31AA	TPC-110W-N31AB	Apr End	May
	TPC-115W-N31YA	TPC-115W-N31YB	Mar End	Apr
	TPC-115W-N31AA	TPC-115W-N31AB	Apr End	May

### Contact Windows

PM	<a href="mailto:Winston.Chen">Winston.Chen/ winston.chen@advantech.com.tw / 511 1093</a>
AE	<a href="mailto:ASG.ACL.PAE@advantech.com">ASG.ACL.PAE@advantech.com</a>