

### 研華股份有限公司 Advantech Co., Ltd.

台北市內湖區瑞光路26巷20弄1號 No.1, Alley 20, Lane 26, Rueiguang Road Neihu, District, Taipei, Taiwan 114, R.O.C. Tel: 886-2-2792-7818 Fax: 886-2-2794-7301 www.advantech.com

# **IIoT Product Change Notice**

The change will be applied on the BB-UHR401 & BB-UHR402. If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

1. Reason for the Change: Component EOL change to new part

2. Affected Products: BB-UHR401 & BB-UHR402

3. Impact on Application: ESD Level change to level 3 (8kv) instead of level 4 (15kv)

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	Yes (CE compliance)
Physical Outlook Change	No
Ordering P/N Change	No
Cut-in Implement	Component Running Change

### 4. Description of the Change(s):

Change product specifications (ESD Level) due to component EOL.

#### 5. Implementation & Schedule of the Change(s):

This change is already in place.

# **Contact Windows**

PM	Carey Wu / CareyCY.Wu@advantech.com.tw	
AE	Ben Lai / Ben.Lai@advantech.com.tw	