



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001096

DATE: 18-Aug-2023

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DG509AAZ/883B	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1321+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1670S+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1673S-3+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1673S-5+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1801+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1801S+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1801S+T&R	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS18030-010+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS18030-050+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1806-010+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1806S-010+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1807+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1807S+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1807S+T&R	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1809-010+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1809-050+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1809-100+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX32520-BNJ+	N/A	17-Aug-2024	13-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX32520-BNS+	N/A	17-Aug-2024	13-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX32520-BNS+T	N/A	17-Aug-2024	13-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX4531EWP+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX4531EWP+T	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX4532CWP+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX4532CWP+T	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX638ACSA+	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Sep-2023

Discontinuance	MAX638ACSA+T	N/A	24-Aug-2024	20-Feb-2025	Part can no longer be manufactured
Discontinuance	VT255BFQX-ADJ	N/A	17-Aug-2024	13-Feb-2025	Part can no longer be manufactured
Discontinuance	VT255FQX-ADJ	N/A	17-Aug-2024	13-Feb-2025	Part can no longer be manufactured