



infrastructure for a connected world

PRODUCT CHANGE NOTIFICATION

Product Category POWER CONNECTORS 20230908-4

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE: ☒ Jul ☒ EMEA ☒ LATAM ☒ 8-Sep-23

IMPACTED REGIONS: ☒ DISCONTINUATION

REASON FOR CHANGE: ☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Introduction of more parts per box for our CB, LAM2, LAMA, LIAS, LICC power and grounding mechanical connector families. They will be moving from 3 -100 pcs per box to 5 -250 pcs per box and will not be able to be ordered in smaller increments.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	9	15
Old product discontinuation date*	2023	12	15

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

IMPACTED PART NUMBER(s)	Replacement Part(s)
CB175-38-QY	CB175-38-L
CB70-14-CY	CB70-14-190
LAM2A1/0-14-6Y	LAM2A1/0-14-Q
LAM2A2/0-14-6Y	LAM2A2/0-14-Q
LAM2A250-38-6Y	LAM2A250-38-X
LAM2A350-12-6Y	LAM2A350-12-5
LAM2B350-12-3Y	LAM2B350-12-8
LAMA1/0-14-QY	LAMA1/0-14-L
LAMA2/0-14-QY	LAMA2/0-14-L
LAMA2-14-QY	LAMA2-14-C
LAMA500-38-6Y	LAMA500-38-5
LAMA6-14-QY	LAMA6-14-C
LIAS250-56-Q	LIAS250-56-X
LICC4-22-C	LICC4-22-TL
LICC4-22TP-C	LICC4-22TP-TL