



07-Nov-2024

PCN #: PCN-24-226011-01

Subject : Cable assemblies

Description of Change : Lorom will cancel TE UL E47891 and CSA LL33523 multiple listing, use Lorom UL E129757-3 and cUL instead.

Reason for Change: Lorom reject to pay maintenance cost of TE UL E47891 and CSA LL33523

Key Dates :

Contact By Date:06-May-2025

Implementation Date:06-May-2025

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1483350-1			
1483351-1			
1483351-2			
1483351-3			
1483352-1			
1483352-2			
1483352-3			
1483353-1			
1483353-2			
1483353-3			
1483355-1			
1483355-3			
1483356-1			
1483356-2			
1483356-3			
1483357-1			
1483357-2			
1483358-1			
1483358-2			
1483358-3			
1820891-1			
1820897-1			
2328346-1			
2347658-1			
2387460-1			
2387474-1			
2387496-1			

2408070-1			
2408070-2			
2408070-3			
2408070-4			
2408070-5			
2458898-1			
2472652-1			
2479752-1			
2479752-2			
2485058-1			
2494033-1			
2494033-2			
2494033-3			
6-161340-6			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by Accuris based on content provided by TE Connectivity.